


(As Proposed By Architect-Over marked with Structural Recommendations)
(Scale 1:100)

PRELIMINARY ISSUE FOR PLANNING & CONSERVATION
DISCUSSION NOT FOR BUILDING CONTROL OR CONSTRUCTION




## PROPOSED GROUND FLOOR PLAN

(Over marked with Alternative Layout's Structural Recommendations)
(Scale 1:100)

PRELIMINARY ISSUE FOR PLANNING & CONSERVATION DISCUSSION NOT FOR BUILDING CONTROL OR CONSTRUCTION

Drw No. 1852 / F02




PROPOSED FIRST FLOOR PLAN

External masonry mortar joints significantly weathered away. Joints will require pointing with NHL lime mortar


with the calculated findings. A ridge purlin is required to reduce the load on the slope purlins and to reduce the horizontal thrust at the top of the masonry walls, particularly as a timber ceiling tie are not present.


PRELIMINARY ISSUE FOR PLANNING & CONSERVATION DISCUSSION NOT FOR BUILDING CONTROL OR CONSTRUCTION





SECTION A-A


SECTION B-B











EDC RECEIVED

ARCHITECTURAL PLANS

FOR REFERENCE

