Mark Nankervis Tree Services Ltd

1 Tresdale Parc, Connor Downs, Hayle, Cornwal TR27 5DX 01736 755218 07894 325 581

info@treeservicesuk.com

TREE CONDITION REPORT ON
SYCAMORE TREE,
VILLNEUVE,
TRELOYHAN MANOR DRIVE,
ST IVES
TR26 2AN



Date of Survey: December 20. 2023. Date of report: January 25. 2023.



Mark Nankervis Chartered Arboriculturalist ICF, M Arbor. A., Advanced Licensed user Quantified Tree Risk Assessment.

INTRODUCTION

I have been asked to prepare a report with regard to T1, a large sycamore (Acer pseudoplatanus) tree at Villneuve with a cluster of what appear to Honey Fungus (Armillaria sp.) fruiting bodies at the base of the tree and with white mycelia and cambial dysfunction consistent with Honey Fungus colonization.

OBSERVATIONS

The fruiting bodies were degraded at the time of inspection but are consistent with Honey Fungus with a shaggy ring around each stalk. There were white mycelia present and the area from which the fruiting bodies emanate has dysfunctional cambium with decay.

The tree is generally if reasonable condition physiologically and structurally but the presence of the fruiting bodies at the base of the tree means that the mycelia of the fungi are active within the tree and probably within the rooting zone in particular . The extent of any root degradation is not possible to determine. My professional opinion is that the generally good condition of the tree physiologically and the fact that this is the first time fruiting bodies have been noticed on the tree make it likely that degradation is not extensive at this point in time.

This is a very large tree growing adjacent to the owner's dwelling. Whilst I do not consider the tree's stability to represent an urgent risk of failure the prognosis for the tree is increased root and cambial degradation which will start to significantly degrade the stability of this tree.

RECOMMENDATIONS

1.1 Remove T1 within 12 months.

nl d

Mark Nankervis MICFor., M. Arbor A, Lantra PTI

Consultant Arborist,

Mark Nankervis Tree Services Ltd

The authority of this letter ceases when any site conditions change, or pruning or other works unspecified in the Report are carried out to, or affecting, the Subject Tree(s). The statements made in this letter do not take into account the effects of extremes of climate, vandalism or accident, whether physical, chemical of fire. Mark Nankervis Tree Services Ltd cannot therefore accept any liability in connection with these factors, nor where prescribed work is not carried out in a correct and professional manner in accordance with current good practice.

The recommendations within this report remain valid for the period stated for re-inspection.

The limit of Mark Nankervis Tree services Ltd's indemnity over any matter arising out of this letter extends only to the instructing client; Mark Nankervis Tree Services Ltd cannot be held liable for any third-party claim that arises following or out of this report. This report remains the intellectual property of Mark Nankervis Tree Services Ltd.

APPENDIX A – Photos

The two Lawsons Cypress trees creating a joint canopy.



Picture 1

T1 Large landscape specimen in generally good condition.



Picture 2

Remains of fruiting bodies with degraded bark and cambium and peripheral decay associated with point of emergence and just above.



Fungal brackets at base of tree and tree in relation to buildings.