ARBORICULTURAL REPORT AND ARBORICULTURAL IMPACT ASSESSMENT to BS 5837:2012 at 45c Turfland Avenue Oldham Lancashire OL2 6EL

Client: Neil & Ann Seville

Client Address: 45c Turfland Avenue Oldham Lancashire OL2 6EL

JCA Ref: 21728/DK

Arboricultural & Ecological Consultants

Contents

1.	Introduction		
1.1	l Purpose of the	Report	
1.2	2 Terms of Refe	ence	
1.3	3 Tree Survey D	etails and Methodology	
2.	Status of the T	'ees	5
3.	Tree Survey De	etails	6
3.1	1 Tree Retention	Categories	
4.	Arboricultural	Impact Assessment (AIA)	7
4.1	l Proposed Deve	lopment	7
4.2	2 Tree Removals	for Development	7
4.3	B Pruning for De	velopment	7
4.4	4 Temporary Pro	tection Measures	7
4.5	5 Implications fo	r Retained Trees	
4.6	6 Remedial Mea	sures	
5.	Summary		
App	oendix 1: Tree	Descriptions and Recommendations	
App	oendix 2: Expla	nation of Tree Descriptions	
App	oendix 3: Gene	al Guidelines	
App	oendix 4: Autho	or Qualifications	
App	oendix 5: Tree	Constraints Plan	
App	oendix 6: Arbo	icultural Implications Plan	

1. Introduction

1.1 Purpose of the Report

- 1.1.1 JCA Limited has been instructed by **Neil & Ann Seville** to survey the trees within influencing distance of **45c Turfland Avenue**, **Oldham** and prepare the findings in a report.
- 1.1.2 This report provides detailed, independent, arboricultural advice on the trees in the context of potential development, conducted in accordance with the guidelines contained within BS5837: 2012 'Trees in relation to design, demolition and construction Recommendations' (BS5837:2012).
- 1.1.3 This report will categorise the trees in accordance with the British Standard, which will help guide the design of potential development in terms of constraints and opportunities related to trees, and provide details of which trees should be retained and which could be removed.
- 1.1.4 The specific design of the proposed development has been considered within the Arboricultural Impact Assessment in **Section 4** and is detailed on the Arboricultural Implications Plan at **Appendix 6**.

1.2 Terms of Reference

1.2.1 For this purpose, an Ordnance Survey based drawing has been used, which forms the basis for the Tree Constraints Plan at **Appendix 5**. Tree positions were not marked on the Ordnance Survey drawing and have therefore been plotted by the surveyor on site. Whilst not as accurate as a topographical survey, our drawing is considered to provide a fair representation of the positions of the trees surveyed. Tree positions should, however, be considered indicative on the Tree Constraints Plan.

1.3 Tree Survey Details and Methodology

- 1.3.1 The survey took place during January 2024 and was conducted by **Dan Kemp** *FdSc* (*Arboriculture*).
- 1.3.2 During this survey, all trees were inspected from ground level. Further investigations, such as a climbed inspection or a decay detection survey, have not been undertaken but may be recommended where deemed appropriate.
- 1.3.3 Only those trees within the site boundary with a stem diameter above 75mm have been included. Where applicable, trees outside the site boundary, but close enough to be affected by a proposed development, are also included.
- 1.3.4 Tree data was collected in accordance with Section 4.4 and Section 4.5 of BS5837: 2012. Full details of all trees surveyed are recorded in the tables at Appendix 1 which can be cross referenced with the Tree Constraints Plan at Appendix 5. A full explanation of the tables can be found at Appendix 2.
- 1.3.5 Measurements were obtained using clinometers, specialist tapes or electronic distometers. Where this was not possible, due to restricted access or other mitigating circumstances, measurements were estimated to the best ability of the surveyor. Where measurements have been estimated, these are clearly highlighted at **Appendix 1** with a '#' symbol.

2. Status of the Trees

- 2.1 A check was made with **Oldham Council** in January 2024 to determine whether any of the trees surveyed as part of this report are subject to any statutory controls.
- 2.2 We are informed that no trees within our survey are subject to any Tree Preservation Orders (TPO) and the site is not located within a Conservation Area.
- 2.3 However, prior to any works being undertaken to trees, those instructing and proposing to carry out the work should satisfy themselves that all appropriate consents are in place to prevent potential breach of legislation.

3. Tree Survey Details

3.1 Tree Retention Categories

3.1.1 Below is a summary of the surveyed vegetation with retention categories identified in accordance with BS5837: 2012. For a full explanation of the retention categories, please refer to **Appendix 2** (Section A2.3).

Retention Category	Trees	Total
В	6	6

- 3.1.2 As a general rule, those trees listed as retention category 'A' or retention category 'B' are the most valuable items of vegetation and as such the removal of these is likely to be met with resistance by the Local Planning Authority (LPA).
- 3.1.3 Those items listed as retention category 'C' are of lesser value and the removal of these is generally less likely to be met with resistance by the LPA.
- 3.1.4 The above information should guide the design in terms of which trees could be removed and which trees should be retained. However, due to changing attitudes with regards to environmental awareness, it should be noted that all trees are considered to have value. As such, it is advised that as many trees as possible be retained, regardless of their BS5837: 2012 retention category status. The retention of trees is further advised to avoid the need to plant replacement specimens, which are usually required to be planted on a 2:1 or 3:1 ratio, and due to their ecological value, which will be assessed as linear habitat units within Biodiversity Metric 3.1.
- 3.1.5 All trees which are to be retained within the proposed development should be inspected on a regular basis in the interests of risk management. They should have a biennial reinspection regime, ideally with each inspection being undertaken during a different season, in order to observe any defects, pests and diseases that are only evident at certain times of year.

4. Arboricultural Impact Assessment (AIA)

4.1 **Proposed Development**

- 4.1.1 The proposed development will consist of the construction of a linear extension adjoining the rear of the property.
- 4.1.2 We have been supplied with **Drawing: 45C Turfland OS** which details the proposed development. The tree data has been overlaid onto the proposed designs to create the Arboricultural Implications Plan, which can be found at **Appendix 6**. This provides the basis for which this Arboricultural Impact Assessment has been prepared.
- 4.1.3 All tree works required to accommodate the proposals are detailed in *italics* in the recommendation columns of the tables at **Appendix 1**. Please note that any required Arboricultural works recommended during the initial survey are also listed in these tables in non-italics.

4.2 Tree Removals for Development

4.2.1 No trees are required to be removed to accommodate the proposed scheme.

4.3 **Pruning for Development**

4.3.1 Where the footprint of the proposed structure passes within the RPA of one of the retained trees, root pruning maybe required, under the supervision of an appointed arboriculturist. Root pruning will accommodate the proposed structure whilst preventing any 'ripping' damage, a problem commonly associated with mechanical excavations. Root pruning is relevant to **T5**.

4.4 **Temporary Protection Measures**

4.4.1 The Protective Barrier

- 4.4.1.1 In order to ensure the effective protection of retained trees during development, a protective barrier will be installed, in accordance with BS5837: 2012 and may comprise of protective fencing and ground protection. This will be the first job on site following the tree removal and pruning works. The fencing should ideally be positioned to protect the entire **Root Protection Area** (**RPA**) of the retained trees, in order to create a **Construction Exclusion Zone** (**CEZ**).
- 4.4.1.2 Routes for pedestrian and site traffic will be located outside, and diverted away from, the RPAs of the retained trees wherever possible. Where this is not practicable, temporary protective surfaces (ground protection) must be laid over the exposed RPAs to reduce/limit soil compaction. The ground protection must therefore distribute the weight of site vehicles, machinery or pedestrians whilst allowing moisture to reach the tree rooting area beneath. Such surfaces must be constructed in accordance with BS5837: 2012.

4.5 Implications for Retained Trees

4.5.1 Works within the RPA

- 4.5.1.1 Where the proposals require work to be undertaken within the RPA of a tree which is to be retained, specialist measures must be adopted during the construction phase to avoid ground compaction and minimise root damage.
- 4.5.1.2 Such areas are highlighted in blue on the Arboricultural Implications Plan at Appendix6 and are addressed in the following sections.

4.5.2 Demolition

4.5.2.1 In this case, no significant demolition activities are required adjacent to retained trees and as such, no mitigation measures are considered necessary.

4.5.3 Access/Construction of Hard Surfacing

4.5.3.1 In this case, the proposed scheme does not require the construction of access roads, driveways or other hard surfaces within the RPA of retained trees. As such no specialised construction techniques/surface treatments will be required for this purpose.

4.5.4 Construction / Foundation Design

- 4.5.4.1 The footprint of proposed structure incurs the RPA of **T5**. In this case, because of the minimal nature of the incursion, it is considered appropriate to undertake root pruning. This will allow for the construction of the building, without causing 'ripping' damage to the roots, a problem commonly associated with mechanical excavation, whilst also preventing the need for specialist foundation designs.
- 4.5.4.2 The water demand of trees can be an important consideration when determining the appropriate foundation design. Due of this, water demands for the trees identified on this site are included in **Appendix 1**, in accordance with **NHBC chapter 4.2**.

4.5.5 Tree Shade

4.5.5.1 Due to the location of the trees, and their distance from to the proposed buildings, issues related to shading are considered to be unlikely and do not require mitigation.

4.5.6 Utilities

4.5.6.1 Details on service routes are not available at this time. Should utilities need to be brought onto the site, these should be routed away from the RPAs of retained trees. Where this is not possible, methodologies on the installation of underground services without damage to tree roots should be considered.

4.5.6.2 All service providers should be consulted prior to commencement of works with the aim of minimising the number of service runs on the site. Any foreseeable incursions to RPAs should be communicated to the appointed arboricultural consultant and the LPA at the earliest possible time to prevent breach of planning conditions and damage to retained trees.

4.5.7 Site Compound

- 4.5.7.1 The site compound, which typically includes the site office, mess facilities, toilets, storage of materials and parking, must be located away from the trees and outside the RPAs.
- 4.5.7.2 Care should also be taken to prevent soil contamination with chemical spillages, including petrol, diesel and oils.

4.5.8 Landscaping

- 4.5.8.1 Proposed fence lines may be constructed within the RPA of a tree if necessary, providing that appropriate considerations are taken with regards to the well-being of the effected tree. As such, no continual trenching is to be undertaken within the RPA (e.g. for small walls onto which panel fencing is installed). Excavations must be kept to a minimum and therefore only fence designs requiring intermittent posts will be acceptable within the RPA. Fences should also be kept as far away from the main stems of the trees as is reasonably possible.
- 4.5.8.2 Any patios, garden paths or other hard surfaces within RPAs which may not be shown on the projected layout (Appendix 6), and in addition to those mentioned in Section 4.5 (hard surfacing) may be constructed using no-dig techniques, providing that they do not cover more than 20% of the RPA and are implemented in accordance with BS5837: 2012. Such surfaces are to be kept as far away from the main stems of the trees as is reasonably practicable. If there is any concern of damaging retained trees, further advice should be sought from a qualified Arboriculturalist.
- 4.5.8.3 No ground level changes are to be undertaken within the RPAs of retained trees, unless otherwise stated or agreed with the appointed Arboricultural Consultant or the LPA. Any requirement to raise/lower ground levels within RPAs must be communicated to these parties at the earliest practical convenience.

4.6 Remedial Measures

- 4.6.1 Protective fencing specifications and on-site positioning, along with details of any necessary specialist construction methods, can be provided in an Arboricultural Method Statement (AMS).
- 4.6.2 The site offers scope for landscaping and tree planting. All areas identified for the new planting should also be protected by fencing during the construction phase to prevent the compaction of the soil.

5. Summary

- 5.1 The arboricultural implications of the development have been considered and discussed in **Section 4**.
- 5.2 All development work carried out in close proximity to trees must be executed in a manner sympathetic to their needs. Otherwise, the condition of the trees may deteriorate in the months and years following development, leading to a loss of amenity and resulting in potentially hazardous trees. Care must therefore be taken to ensure that the retained trees are suitably protected.
- 5.3 In accordance with Section 6.1 of BS 5837: 2012, the next stage on this site should be the preparation of an Arboricultural Method Statement (AMS), to ensure that all the retained trees survive the development process. An AMS details which trees are to be removed, which trees are to be retained and any other tree works which are required to facilitate development. The AMS will also advise on temporary protective barriers, temporary ground protection, site supervision, location of services and it will detail specialist construction techniques.
- 5.4 In accordance with Section 6.3 of BS 5837: 2012, site supervision at key stages of the development is likely to be advisable.
- 5.5 The data gained during the survey provides an indication of the health of the trees. However, it does not enable a comprehensive assessment of their condition over time. Trees are living organisms which are affected by many factors including weather conditions, diseases/disorders, light levels and human activities. Due to this, this report is only valid for a period of 1 year from the date of issuing. Should an update or revision of this report be required outside of this time period, JCA may require a further site visit to ensure that the condition of the trees has not significantly changed. It is advised that the trees are inspected regularly, in the interests of risk management.

Appendices

Appendix 1: Tree Descriptions and Recommendations

Appendix 1

Tree Descriptions and Recommendations

Tree Ref	Age Common Name Botanical Name	Height (m)	Diameter (cm)	Crown Height (m)	Height (m) and Direction of the Lowest Branch	No. of Stems	Crown Spread N W E S	Observations	Recommendations	Priority	Physiological Condition	Structural Condition	Amenity Value	NHBC Water Demand	Life Expectancy (yrs)	Retention Category
Т 1	Mature Downy Birch Betula pubescens	14 to 18 #	48	2 to 3 #	2 to 3 # N/A	1	5# 4# 5.5# 5#	Vertical main stem and spreading crown. Minor mower damage.	No action required n/a	N/A	GOOD	GOOD	MOD	LOW	40+	B 1
T 2	Mature Downy Birch Betula pubescens	14 to 18 #	31	2 to 3 #	2 to 3 # N/A	1	3# 3# 4# 4#	Vertical main stem and spreading crown. Minor mower damage.	No action required n/a	N/A	GOOD	GOOD	MOD	LOW	40+	B 1
Т 3	Mature Downy Birch Betula pubescens	14 to 18 #	29	2 to 3 #	2 to 3 # N/A	1	4# 3# 3# 2#	Vertical main stem and spreading crown. Minor mower damage. Slight lean.	No action required n/a	N/A	GOOD	GOOD	MOD	LOW	40+	B 1
T 4	Mature Downy Birch Betula pubescens	14 to 18 #	30	2 to 3 #	2 to 3 # N/A	1	6# 5# 3# 3.5#	Vertical main stem and spreading crown. Minor mower damage.	No action required n/a	N/A	GOOD	GOOD	MOD	LOW	40+	B 1
Т 5	Mature Downy Birch Betula pubescens	14 to 18 #	42	2 to 3 #	2 to 3 # N/A	1	4# 4# 3# 3#	Vertical main stem and spreading crown. Minor mower damage.	No action required Root prune to facilitate development. n/a	N/A	GOOD	GOOD	MOD	LOW	40+	B 1
Τ6	Mature Downy Birch Betula pubescens	14 to 18 #	35	2 to 3 #	2 to 3 # N/A	1	4.5 # 3.5 # 4 # 3 #	Vertical main stem and spreading crown. Minor mower damage.	No action required n/a	N/A	GOOD	GOOD	MOD	LOW	40+	B 1

Appendix 2: Explanation of Tree Descriptions

A2.1 Measurements/Reference Information

- A2.1.1 *REF NUMBER*. All items surveyed are allocated a reference number preceded with a letter, identifying the type of vegetation surveyed: T = an individual tree, G = a group of trees or an area of vegetation, W = woodland, H = a hedgerow.
- A2.1.2 SPECIES: COMMON AND BOTANICAL NAME. The common and botanical names of the species present are noted. If the species is not clear or identifiable, then a general common name and genus will be noted.
- A2.1.3 *AGE CLASS* of the tree is described as young, semi-mature, early-mature, mature, overmature, veteran or dead.
- A2.1.4 HEIGHT of the tree is measured in metres from the stem base to the top of the crown.
- A2.1.5 *CROWN HEIGHT* is an indication of the height above ground level at which the crown begins.
- A2.1.6 *STEM DIAMETER* is measured at 1.5 metres above (higher) ground level. Where the tree is multi-stemmed at this point; diameter measurements are taken for each stem. If more than five stems are present, an average stem diameter is taken. If for whatever reason it is not practical to measure multiple-stemmed trees in this way, the diameter is measured close to ground level, just above the root buttress.
- A2.1.7 *CROWN SPREAD* is measured from the centre of the stem base to the tips of the branches to all four cardinal points.
- A2.1.8 *HEIGHT AND DIRECTION OF LOWEST BRANCH*. The height and direction of the lowest significant branch is noted because of potential issues relating to clearances and the need for tree pruning.
- A2.1.9 *NHBC WATER DEMAND*. The water demand of each tree, as listed in NHBC Standards 2010 Chapter 4.2 'Building near trees'. This is included to aid structural engineers, architects and other members of the design team as it determines foundation depth and other considerations with regard to trees.

A2.2 Evaluations

- A2.2.1 *PHYSIOLOGICAL CONDITION* is classed as good, fair, poor, or dead. This is an indication of the health and vitality of the tree and takes into account vigour, presence of disease and dieback.
- A2.2.2 *STRUCTURAL CONDITION* is classed as good, fair or poor. This is an indication of the structural integrity of the tree and takes into account significant wounds, decay and quality of branch junctions.
- A2.2.3 *LIFE EXPECTANCY* is classed as; 0, less than 10 years, 10+ years, 20+ years, or 40 + years. This is an indication of the minimum number of years before removal of the tree is likely to be required.
- A2.2.4 *AMENITY VALUE*. A general indication is given in respect to the amenity/landscape value of the tree/group within the surrounding area.
- A2.2.5 *PRIORITIES.* A priority rating is given concerning the time periods in which the recommended works should be undertaken. LOW priority works should be undertaken within 12 months of the survey, MOD (moderate) priority works should be undertaken within 6 months and HIGH priority works should be completed as soon as practically possible. If no works are recommended, N/A (not applicable) will be used.

A2.3 Retention Categories

A2.3.1 A (marked green on the Tree Constraints Plan) = Trees of high quality.

These trees are of high quality and value with a good life expectancy (usually with an estimated remaining life expectancy of 40 years).

A2.3.2 B (marked in blue on the Tree Constraints Plan) = Trees of moderate quality.

These trees are of moderate quality and value with a reasonable life expectancy (usually with an estimated life expectancy of at least 20 years).

A2.3.3 C (marked in grey on the Tree Constraints Plan) = Trees of low quality.

These trees are of low quality and value but which are in adequate condition to remain or are young trees with a stem diameter below 15cm (usually with an estimated life expectancy of at least 10 years).

- A2.3.4 Trees categorised as retention category 'A', 'B' or 'C' are then justified by being further divided into 3 subcategories:
 - 1 = Mainly arboricultural qualities.
 - 2 = Mainly landscape qualities.
 - 3 = Mainly cultural values, including conservation value.

A2.3.5 U (marked in red on the Tree Constraints Plan) = Trees usually unsuitable for

retention due to poor condition.

These trees are in such a condition that they cannot be realistically retained as living trees in the context of the current land use for longer than 10 years. This may be due to any of the following:

- 1) Failure is likely due to serious, irredeemable, structural defects.
- 2) Removal of other category U trees will render them exposed and unstable.
- 3) They are in serious, overall decline or are dead.
- 4) They are of low quality and suppressing adjacent trees of better quality.
- 5) Diseases are present which may affect the health of adjacent trees.

These trees are to be removed or managed in a way which reduces their risk of failure, where they have high ecological value, such as in a woodland setting.

Appendix 3: General Guidelines

- A3.1 All tree work must be undertaken to BS 3998: 2010 '*Recommendations for tree work*' or other recognised industry practice.
- A3.2 Staff carrying out the work must be qualified, experienced and ideally be Arboricultural Association approved contractors. They should be covered by adequate public liability insurance.
- A3.3 This report is based upon a visual inspection. The consultant shall not be responsible for events which happen after this time due to factors which were not apparent at the time, and the acceptance of this report constitutes an agreement with the guidelines and the terms listed in this report.
- A3.4 Any defects seen by a contractor or the employer that were not apparent to the consultant must be brought to the consultant's attention immediately.
- A3.5 No liability can be accepted by JCA in respect of the trees unless the recommendations of this report are carried out under the supervision of JCA and within JCA's timescale.
- A3.6 It is advisable to have trees inspected by an arboricultural consultant regularly.

Appendix 4: Author Qualifications

Principal Consultant and Managing Director

Jonathan Cocking *F.R.E.S., Tech. Cert. (Arbor.A), PDipArb (RFS) FArborA CBiol MSB. MICFor.* Jonathan is a Registered Consultant and Fellow of the Arboricultural Association and sits on its Professional Committee. He has 31 years' experience in the Arboricultural profession and served for eight years as Senior Arboriculturist with a large local authority before establishing JCA in 1997. Jonathan has since developed JCA's portfolio of services and its extensive client base. He is a Chartered Biologist, a Chartered Arboriculturalist and an Expert Witness with much experience of litigation work.

Technical Director

Toby Thwaites *BSc (Hons), HND (Arboriculture), MArborA.* Toby joined JCA in 1998 after graduating in Ecology at the University of Huddersfield and has since graduated in Arboriculture at the University of Central Lancashire. A former JCA team leader and Consulting Arboriculturist, Toby is now Technical Director and oversees all office and on-site activities at JCA and is on hand to offer technical support and advice.

Operations Director

Charles Cocking *FdSc (Arboriculture), MArborA.* Charles joined JCA in January 2014 having previously worked for the company on a part time basis during 2013. Charles obtained his Foundation Degree in Arboriculture at Askham Bryan College, York, and is a Professional Member of the Arboricultural Association. Charles now oversees all internal operations for the company.

Consulting Staff: Arboriculture

Andrew Bussey. Andrew started working in consultancy at JCA in 2006 having spent 12 years working as an arborist for various private companies before joining a Local Authority forestry team. He has various NPTC qualifications, is QTRA qualified and is a LANTRA Accredited Professional Tree Inspector.

Emily Wilde *FdSc (Arboriculture)*. Emily joined JCA having previously worked for various private tree surgery and consultancy companies over the past 8 years. She initially obtained a ND in Forestry & Arboriculture, followed by a FdSc in Arboriculture at Askham Bryan College, York. Emily has various NPTC certificates and is QTRA qualified.

Mick Eltringham *ND (Forestry).* Mick joined JCA after spending 12 years working in the industry for various private companies in the north and south of England. He has also spent the last five years working as a consultant for two canopy research projects in the Amazon Rainforest, working with Oxford University and the University of Arizona. He has various NPTC Qualifications.

Dan Kemp *FdSc (Arboriculture), BTEC National Diploma(Arboriculture), National Certificate In Horticulture, City & Guilds In Horticulture.* Dan joined JCA in February 2019 with nearly 30 years' experience in arboriculture with extensive Botanical and Mycological expertise. He worked as a London Tree Officer for 12 years and in several arboricultural and horticultural management posts, specialising particularly in tree risk assessments and tree related subsidence.

Luke Wickham *FdSc (Arboriculture and Urban Forestry), TechArborA.* Luke joined JCA in 2021 after obtaining his Foundation Degree in Arboriculture and Urban Forestry at Askham Bryan College. Having previously worked within the industry for the past 4 years, running his own small business and sub-contracting for local firms, Luke brings a sound knowledge and understanding of the practical and academic sides of the industry.

Andrew McPhaden *BSc (Hons), TechArborA.* Andrew joined JCA in 2022 having spent 5 years working as an Arborist for various private companies in both the UK and Germany. During his time abroad he obtained the European Tree Worker Certification along with a tree inspector certification from the Forschungsgesellschaft Landschaftsentwicklung Ladschaftsbau. He brings a strong understanding of the practical sides of the industry and holds various NPTC qualifications.

Administrative Staff

Catherine Cocking Accounts Manager. **Kelly Saunders** Accounts Assistant.

Lorraine Spink Administrative Assistant. Adie Gray I.T. Officer.

Appendix 5: Tree Constraints Plan



Root Protection Area: RPA THE ROOT PROTECTION AREA SHOULD IDEALLY REMAIN UNDISTURBED IF THE TREE IS TO BE RETAINED.

×5

×5

NACANO ALENCE

THE DEVELOPMENT PROPOSALS SHOULD THEREFORE BE DESIGNED TO AVOID THE RPA OF ANY TREE WHICH IS TO BE RETAINED.

IF IT IS NECESSARY FOR THE DEVELOPMENT TO ENCROACH INTO THE RPA OF A TREE WHICH IS TO BE RETAINED THEN SPECIALIST CONSTRUCTION TECHNIQUES AND MATERIALS MUST BE CONSIDERED.





Lancashire, OL2 6EL. JCA REF: 21728/DK SCALE : 1:200 PAPER SIZE : A3								
SURVEYED BY: DK	DRAWN	BY: DK	APPROVED BY: ME					
BRITISH STANDARD 5837:2012: 4.5 RETENTION CATEGORIES Detailed definitions of these categories are at Appendix 2 of our report. N.B. These categories do not necessarily represent or correspond to necommendations for action made in this report								
\bigcirc	CATEG 'RETEN	ory A: Tion Mos	ST DESIRABLE'					
\bigcirc	CATEG	ory B: Tion des	IRABLE'					
\bigcirc	CATEG TREE V RETAIN	ORY C: VHICH CC IED'	OULD BE					
\bigcirc	CATEG TREE F	ORY U: FOR REMO	DVAL'					
•	STEM C BE RET	OF TREE T AINED	0					
•	STEM C BE REN	OF TREE T NOVED	Ö					
ROOT PROTECTION AREA								
Arboricultural & Ecological Consultants								

Appendix 6: Arboricultural Implications Plan





Appendix 6: Arboricultural Implications Plan									
ADDRESS: 45c, Turfland Avenue, Oldham, Lancashire, OL2 6EL. JCA REF: 21728/DK									
SCALE : 1:200 PAPER SIZE : A3									
\bigcirc	TREE TO BE RETAINED								
\bigcirc	TREE TO BE REMOVED								
•	STEM OF TREE TO BE RETAINED								
•	STEM OF TREE TO BE REMOVED								
	ROOT PROTECTION AREA ROOT PROTECTION AREA ENCROACHED BY THE PROPOSED DEVELOPMENT								
	PROPOSED DEVELOPMENT								
Arboricultural & Ecological Consultants									

I hope that this report provides all the necessary information, but should any further advice be needed please do not hesitate to contact the author.

D Кетр

Dan Kemp FdSc (Arboriculture).

29th January 2024

For and on behalf of JCA Ltd

Registered Office:

Unit 80 Bowers Mill Branch Road Barkisland Halifax HX4 0AD

Tel. 01422 376335 Fax. 01422 376232 Email: info@jcaac.com

www.jcaac.com

JCA Ltd. Arboricultural and Ecological Consultants Professional Tree and Ecology Advice nationwide

ARBORICULTURAL SERVICES

Guidance for Architects and Developers

- British Standard 5837 Tree Surveys
- Arboricultural Implication Assessments (AIA)
- Arboricultural Method Statements (AMS)

Tree Advice for the Legal Profession

- Subsidence Litigation
- Personal Injury and Accident Investigation
- Expert Witness, Planning Inquiries and Appeals

Advice for Engineers, Loss Adjusters and Insurers

- Tree Surveys for Subsidence
- Heave Assessment
- Tree Root Identification

Veteran Tree Management

- Ancient Woodland Management
- Veteran Tree Management

Advice for Local Authorities and Social Housing

- Tree Safety Surveys
- Specialist Decay Detection
- Landscape and Orchard Design

Tree Health and Pest and Disease Management

- Pest and Disease Surveys
- Tree Health Checks
- Disease Mitigation and Control

ECOLOGICAL SERVICES

Ecological Pre-Planning Services

- Phase 1 Habitat Surveys
- Great Crested Newt eDNA Sampling
- Protected Species: Bat, Wintering and Nesting Bird, Badger, Amphibian, Otter, Water Vole, White-Clawed Crayfish, Dormice and Reptile Surveys.
- Preparation for Environmental Impact Assessment (EIA)
- Invasive Species Surveys
- Code for Sustainable Homes

Ecological Post-Planning Services

- Biodiversity Enhancement Plans
- Protected Species Mitigation
- Ecological Management (Bat and Bird box installation and inspection)

HEAD QUARTERS:

Unit 80 Bowers Mill, Branch Road, Barkisland, Halifax, HX4 0AD. Tel: 01422 376335 Email: info@jcaac.com Website: www.jcaac.com



Company Reg No. 05005041 VAT No. 686 4674 78