CONDITIONS

Presentation letter

42 Cleveland Square Flat I London WI 6DA

Reply to conditions to planning application permits

19/08373/FULL and 19/08374/LBC

DATE

12-01-2021

RETROUVIUS

Retrouvius Design Limited | +44(0)20 8960 8676 2A Ravensworth Road London NW10 5NR chiara@retrouvius.com | retrouvius.com

Condition presentation letter



1.0 Conditions

Reply to condition n.3 for 19/08373/FULL and 19/08374/LBC

I) Joinery profiles for new rear windows Please refer to joinery drawings:

```
RTV_149_Condition_03_01
RTV_149_Condition_03_02
RTV_149_Condition_03_03
```

submitted alongside this letter.

The proposed mouldings would replicate what on original windows The proposed glazing bars are lambs tongue with external putty.

2) Architrave to new entrance from landing Please refer to drawing RTV_149_Condition_03_04 submitted alongside this letter. The existing architrave for the new entrance door will be kept in situ. No new architrave need it.

3) Works to the leaded glazing in the rear room of no.42 Please refer to drawing RTV_149_Condition_03_05 submitted alongside this letter.

The specialize glazing company who will take on the restoration of these glazed panels is named: Lead & Light
35 A Hartland Rd
Camden, London
NWI 8DB

Restoration work is always focused on retaining as much as possible of the original window and only changing glass that is either broken or re-placed previously with mis-matched glass that is not close to the original.

Glazed panel 01

Top LHS corner. Remove from timber frame and re-lead complete window using existing glass. Replace No.4 light green damaged glass with Tatra clear antique similar to existing. Replace No 3 clear texture background glass with old glass in stock similar to existing. Re-cement and waterproof panels and re-glaze into timber frame using linseed oil putty as per original.

Glazed panel 02

Replace glass from previous restoration when ordinary glass was fitted in place of "Roundel" is 3x areas.

Replace 3x broken and mis-matched glass with old glass as per existing. The Door in three sections is in otherwise good conditions and not extra work is required.

Condition presentation letter



2.0 Associated Documents

149_Condition_03_01	(Windows- Photos)
149 Condition 03 02	(Windows - Sash)
149_Condition_03_03	(Windows - Casement)
149 Condition 03 04	(Architrava)

149_Condition_03_04(Architrave)149_Condition_03_05(Lead rear w (Lead rear window)