150mm full stone indent		Area requiring repointing 3mm ashlar joint	ALL GUTTERS TO EXISTING BUILDINGS TO BE REPLACED
Ashlar faced		NHL 5	EXISTING SLATE ROOF REPAIRS AS PER [PP]03 AND NBS H62 LEAD REPAIRS AS PER
150mm full stone indent Rubble faced		Window mesh installed	DETAIL SERIES 37 AND NBS H71 STONE INDENTS
Full-stone tracery /	[]	Movement crack to be	GENERALLY A MINIMUM OF 150MM DEEP AND CARRIED OUT IN CORNCOCKLE SANDSTONE - SAMPLE TO BE APPROVED BY CA AND HES ON SITE
moulded / mullion indent		repaired	Full extent of stone repairs and repointing to be agreed on site once scaffold is erected, stone repairs and
Area requiring repointing 6mm Rubble joints NHL 3.5 - 1:2		Zone where service penetrations are acceptable in principle, all new cores require CA and HES sign off	repointing not to commence until sign off for scheme is received from HES.
Area requiring repointing 6mm+ Rubble joints NHL 3.5 - 1:2.5			
Area requiring repointing 3mm ashlar joint NHL 3.5			

