Remove perspex and fixings. Restore leaded glazing as schedule. Locally indent fixing holes after removing screws [2] 2 2

Main Church, North Facing Lancet - Vented Bell Tower

Notes / Key:

Stone indents: Sandstone to best match existing as determined by petrographic analysis. Unless otherwise indicated repairs to be minimum depth of 100mm (type 4/5 to be agreed on site).

Stone repairs to be carried out whilst stained glass has been removed from site by Rainbow Glass.

All stone indents to fixed with 6mm SS dowels to SE spec.

Team to agree methodology for replacement and schedule of works to avoid destabilisation of structure during indents.

Do not scale from this drawing.
All existing dimensions to be checked on site prior to commencement of works or manufacturing of components.
Any discrepancies to be brought to the attention of the architect - if in doubt, ask.

This drawing is the copyright of John Gilbert Architects Ltd. No copying or distribution of this drawing or any part thereof is permitted without prior written permission.



201 White Studios, 62 Templeton Street, Glasgow, G40 1DA Tel: 0141 551 8383 Web: www.johngilbert.co.uk

ABOVE ADVENTURE

Project

WOODSTOCK STREET CHURCH

Title

NORTH FACING LANCET - VENTED BELL TOWER

Project Status
TENDER

Job No Scale at A3
03749 NTS

Drawn by Date of issue
SP

Rev. Ammendment Date

A REFERENCE NUMBERS ADDED 07.01.20

Drg No. **[21]10**

Rev

A