

CRACK MONITORING

for Subsidence Management Services

89 West End, March, PE15 8DJ

| | |
|-------------------|---|
| Client: | Subsidence Management Services |
| Client Contact: | Ian Hanson |
| Claim Number: | 500139467 |
| Client Reference: | IFS-LBG-SUB-19-0084888 |
| Policy Holder: | Mr Terence Redhead and Mrs Rachel Redhead |
| Report Date: | 13 August 2020 |
| Our Ref: | M15019 |

Crack Monitoring Readings


The following table shows the reading levels of the Crack Monitoring Stations.

| Date | A=B (H) | B=C (D) | A=C (V)(C) | Crack Width |
|--|---------|---------|------------|-------------|
| C1 - INT- Above Door Between Lounge and Rear Lounge | | | | |
| 7 January 2020 | 80.61 | 109.60 | 76.40 | 1.50 - 1.40 |
| 3 March 2020 | 80.76 | 109.63 | 76.43 | |
| 21 April 2020 | | | | |
| 12 June 2020 | 80.88 | 109.71 | 76.48 | 1.70 - 1.10 |
| 5 August 2020 | 81.16 | 110.20 | 76.11 | 2.00 - 1.90 |
| Date | A=B (H) | B=C (D) | A=C (V) | Crack Width |
| C2 - EXT- Below Front Door | | | | |
| 7 January 2020 | 94.56 | | | 4.70 |
| 3 March 2020 | 94.56 | | | |
| 21 April 2020 | 94.62 | | | |
| 12 June 2020 | 95.01 | | | |
| 5 August 2020 | 95.60 | | | 4.70 |
| Date | A=B (H) | B=C (D) | A=C (V)(C) | Crack Width |
| C3 - EXT- RHS above Front Window | | | | |
| 7 January 2020 | 88.23 | 110.91 | 66.14 | 2.10 - 3.70 |
| 3 March 2020 | 88.20 | 110.72 | 66.02 | |
| 21 April 2020 | 88.33 | 110.82 | 66.01 | |
| 12 June 2020 | 88.64 | 111.12 | 66.07 | |
| 5 August 2020 | 88.87 | 111.39 | 66.13 | 3.50 - 3.60 |
| Date | A=B (H) | B=C (D) | A=C (V) | Crack Width |
| C4 - EXT- Above Front Door RHS | | | | |
| 7 January 2020 | | | 77.76 | 2.40 |
| 3 March 2020 | | | 77.62 | |
| 21 April 2020 | | | 77.90 | 2.50 |
| 12 June 2020 | | | 78.34 | |
| 5 August 2020 | | | 79.24 | 5.00 |

Crack Monitoring Difference Graphs

The following graphs display the progressive movement that each Crack Monitoring Station recorded at each separate site visit date to give an overall look at how much the property is moving.


C1 - INT- Above Door Between Lounge and Rear Lounge




C2 - EXT- Below Front Door



C3 - EXT- RHS above Front Window



C4 - EXT- Above Front Door RHS



Site Visit Notes

Site Visit: 7 January 2020

Technician has strongly advised a deep datum.

Site Visit: 3 March 2020

Level stations 2a and 4a added this visit.

Site Visit: 21 April 2020

Point 1 is solid and double checked.

Site Visit: 5 August 2020

Movement noted and checked- stations secure.