## BICESTER TREE SERVICES LTD: ARBORICULTURAL SURVEY REPORT

## Appendix 2

Site: Brill Vicarage HP18 9ST

Date: 1st February 2021

| Tag<br>No. | Location          | Species     | Diameter<br>(cm) | Height<br>(m.) | Age<br>Class | Condition   | Recommendations                                      | Priority months |
|------------|-------------------|-------------|------------------|----------------|--------------|---|--|-----------------|
| 1          | Adjacent to drive | Malus       | 15               | 5              | M            | Good form and condition. Multi-stemmed from 1m, regularly pruned to maintain the crown spread due to the proximity of the drive.  | Crown reduce by 1.5m                                 | MR              |
| 2          | Adjacent to drive | Cotoneaster | Av 5             | 6              | M            | Fair. Low vitality in suppressed lateral stems.   | Crown raise by removing several suppressed laterals. | MR              |
| 3          | Rear garden       | Cherry      | 40               | 12             | М            | Good vitality. Poor form including a low lateral at 1.5m, heavy lean towards the garden, in close proximity to the garden wall. Slight structural damage, long term retention will result in further structural damage. | Crown raise to 4m, removing the low lateral at 1.5m  | MR              |
| 4          | Rear garden       | Goat Willow | Av 15            | 6              | D            | Dead. Multi-stemmed.  | Fell and reduce the adjacent Pyracantha shrub to 2m. | 12              |
| 5          | Rear garden       | Birch       | 25               | 12             | M            | Good condition and vitality.  | No Work Required                                     | -               |
|            |                   |             |                  |                | _            | END OF SURVEY   |  |                 |