


I Stable Yard Elevation 2 (SE2) Repairs w/Demo **2200**/ 1:100



2 Stableyard Elevation I (SEI) Repairs w/Demo **2200** I : 100

Type AI - Repointing standard brickwork joints - 50%

Type B1 - Indent repair to brickwork. - 15%

Type CI - Doff clean - 100%

Drawings are based on survey data and may not accurately represent what is physically present.

Do not scale from this drawing. All dimensions are to be verified on site before proceeding with the work.

All dimensions are in millimeters unless noted otherwise.

Purcell shall be notified in writing of any discrepancies.

Key Plan not to scale

Repair Key

Drawings are to be read in conjunction with the Roof repair drawing and the Structural Engineer reports.

<u>Generally</u>

All external masonry elevations are to recieve DOFF treatment to clean algae and biological growths off masonry.

All copings to be checked. Allowance generally to remove embedded metalwork, rebed and pin copings and point joints. Allowance made for replacement and indents.

All external fixtures and fittings are to be removed from the elevations and made good.

An additional provisional sum of 20% to entire works noted should be allowed above items stated to cover access restrictions.

Type A1 - Repointing standard brickwork joints in lime mortar Type A2 - Repointing fine ashlar joints in lime mortar.

Type BI - Indent repair to brickwork.

Handmade clay brickwork to match historic brickwork in coursing, size, colour and texture.

Type B2 - Indent repair to Stone Ashlar Stonework to match colour, texture, grain and density of historic stonework

Type B3 - Indent repair to stone moulding Stonework to match colour, texture, grain, density and profile of existing

stonework. Stainless steel pins.

Type B4 - Composite Indent Repair to stone moulding (surround or string course)

Composite repair to include for removal of existing embedded ironwork, replacement of stainless steel pins at regular centres. Historic material to undergo analysis for composition.

Type B5 - Defrass stonework and complete mortar repair. Mortar repair to match moulding, colour, texture of adjacent stonework.

Type CI - Doff clean


Type C2 - Remove paint off stonework with a poultice paint remover and Doff clean.

Type C3 - Clean stonework

Tyoe C4 - Poultice clean to remove surface salts within masonry

Type D - Remove fixture off elevation and make good masonry / Type D2 - Remove fitting from wall and complete stone / brick indent.

Type E - Pin Crack to stonework



CLIENT

Colin Shenton

DATE

PROJECT

Cuerden Hall, Chorley

JOB NUMBER

240729

TITLE

PURCELL

Proposed Repair Elevations

DESCRIPTION

SIZE SCALE LAST REVISED DRAWN CHECKED AIL As Shown 07/04/2021 ZB

SUITABILITY/REASON FOR ISSUE S04 - For Planning

DRAWING NUMBER 240729-PUR-00-XX-DR-A-2200

St James', 79 Oxford Street, Manchester, MI 6FQ

© PURCELL 2019. PURCELL ® IS THE TRADING NAME OF PURCELL ARCHITECTURE LTD.