



Observed floodwater flow paths from millstream through WODC car park and adjacent field during the winter season.

The car park drain is inadequate and, consequently, a lake forms in the car park at the central point during heavy storms and rain.

Existing field drainage swale.

Drain into Spillway

| No. | Date. | Revision. |
|-----|----------|-------------------|
| A | Jan 2019 | Mill Stream named |

NOT
This drawing is copyright
Figured dimensions must be taken in preference to scaled dimensions.

PROPOSED CAR PARK EXTENSION GULDENFORD BURFORD

1:50
BURF2018 CP A

MJB