

Building Recording - First Floor


Internal Doors

Showing existing photos, noted location, frame condition, leaf condition and proposed refurbishment works

The doors within the building are predominantly non original or have been re positioned. The 1840's section the building has also had walls and door way re positioned and replaced. It is generally aimed to retain all doors where possible, but where doors are to be removed it is proposed to re use and re position the frame and architrave.

For the door locations, please see the floor plans attached along with this building record.

Door Numbers:



First Floor Internal Doors



Internal Photo D101i

Photo Location - Brecon Dorm - Door Number **D101** - See floor plans for location

Located with 1840's section of the building

Door leaf - Presumed non original - Good condition

Frame and Architrave - Presumed original - Good condition

Glass - None

Proposed works:

- Refurbish and repaint frame

Door leaf replaced

First Floor Internal Doors



Internal Photo D102i

Photo Location - Brecon Dorm - Door Number **D102** - See floor plans for location

Located with 1840's section of the building

Door leaf - Presumed non original - Good condition

Frame and Architrave - Presumed original - Good condition

Glass - None

Proposed works:

- Removed in proposed, see proposed plans 001158 _ **111**

First Floor Internal Doors



Internal Photo D103i

Photo Location - Brecon Dorm Wc - Door Number **D103** - See floor plans for location

Located with 1840's section of the building

Door leaf - Presumed non original - Good condition

Frame and Architrave - Presumed non original - Good condition

Glass - None

Proposed works:

- Removed in proposed, see proposed plans 001158 _ **111**

19th of March 2021.

First Floor Internal Doors



Internal Photo D104i

Photo Location - Wc - Door Number **D104** - See floor plans for location

Located with 1840's section of the building

Door leaf - Presumed non original - Good condition

Frame and Architrave - Presumed original - Good condition

Glass - None

Proposed works:

· None

First Floor Internal Doors



Internal Photo D105i

Photo Location - Back stairs - Door Number **D105** - See floor plans for location

Located with 1840's section of the building

Door leaf - Presumed non original - Good condition

Frame and Architrave - Presumed original - Good condition

Glass - Vision panel

Proposed works:

- Removed in proposed, see proposed plans 001158 _ **111**

First Floor Internal Doors



Internal Photo D106i

Photo Location - Landing - Door Number **D106** - See floor plans for location

Located with 1840's section of the building

Door leaf - Presumed non original - Good condition

Frame and Architrave - Presumed original - Good condition

Glass - None

Proposed works:

· None

First Floor Internal Doors



Internal Photo D107i

Photo Location - Lecture room - Door Number **D107** - See floor plans for location

Located with 1990's section of the building

Door leaf - Presumed original - Good condition

Frame and Architrave - Presumed original - Good condition

Glass - Safety Glass

Proposed works:

- Removed in proposed, see proposed plans 001158 _ **111**

First Floor Internal Doors



Internal Photo D108i

Photo Location - Nador Dorm - Door Number **D108** - See floor plans for location

Located with 1840's section of the building

Door leaf - Presumed non original - Good condition

Frame and Architrave - Presumed original - Good condition

Glass - None

Proposed works:

- Removed in proposed, see proposed plans 001158 _ **111**

First Floor Internal Doors



Internal Photo D109i

Photo Location - Wc - Door Number **D109** - See floor plans for location

Located with 1840's section of the building

Door leaf - Presumed non original - Good condition

Frame and Architrave - Presumed non original - Good condition

Glass - None

Proposed works:

- Removed in proposed, see proposed plans 001158 _ **111**

First Floor Internal Doors



Internal Photo D110i

Photo Location - Wc - Door Number **D110** - See floor plans for location

Located with 1750's section of the building

Door leaf - Presumed non original - Good condition

Frame and Architrave - Presumed original - Good condition

Glass - None

Proposed works:

- To enable a new ensuite bathroom and greater amenity for the users the existing opening is to be filled in a reversible manner, retain all existing frame and architrave. See proposed plans 001158 _ **111**

First Floor Internal Doors



Internal Photo D111i

Photo Location - Landing - Door Number **D111** - See floor plans for location

Located with 1750's section of the building

Door leaf - Presumed non original - Good condition

Frame and Architrave - Presumed original - Good condition

Glass - None

Proposed works:

· None

First Floor Internal Doors



Internal Photo D1112i

Photo Location - Landing - Door Number **D112** - See floor plans for location

Located with 1750's section of the building

Door leaf - Presumed non original - Good condition

Frame and Architrave - Presumed original - Good condition

Glass - None

Proposed works:

· None

19th of March 2021.

First Floor Internal Doors



Internal Photo D1113i

Photo Location - Landing - Door Number **D113** - See floor plans for location

Located with 1750's section of the building

Door leaf - Presumed non original - Good condition

Frame and Architrave - Presumed original - Good condition

Glass - None

Proposed works:

- To enable a new ensuite bathroom and greater amenity for the users the existing opening is to be filled in a reversible manner, retain all existing frame and architrave. See proposed plans 001158 _ **111**

First Floor Internal Doors



Internal Photo D1114i

Photo Location - Landing - Door Number **D114** - See floor plans for location

Located with 1750's section of the building

Door leaf - Presumed non original - Good condition

Frame and Architrave - Presumed original - Good condition

Glass - None

Proposed works:

· None

First Floor Internal Doors



Internal Photo D115i

Photo Location - Landing - Door Number **D115** - See floor plans for location

Located with 1750's section of the building

Door leaf - Presumed non original - Good condition

Frame and Architrave - Presumed original - Good condition

Glass - None

Proposed works:

· None

First Floor Internal Doors



Internal Photo D116i

Photo Location - Bedroom 1 - Door Number **D116** - See floor plans for location

Located with 1750's section of the building

Door leaf - Presumed non original - Good condition

Frame and Architrave - Presumed original - Good condition - removed and reused in building

Glass - None

Proposed works:

- To enable a new ensuite bathroom and greater amenity for the users the existing opening is to be filled in a reversible manner, retain all existing frame and architrave. See proposed plans 001158 _ **111**

First Floor Internal Doors



Internal Photo D117i

Photo Location - Stairwell - Door Number **D117**- See floor plans for location

Located with 1750's section of the building

Door leaf - Presumed non original - Good condition

Frame and Architrave - Presumed original - Good condition

Glass - None

Proposed works:

- To enable a new ensuite bathroom and greater amenity for the users the existing opening is to be filled in a reversible manner, retain all existing frame and architrave. See proposed plans 001158 _ **111**


Second Floor

Internal Doors

Showing existing photos, noted location, frame condition, leaf condition and proposed refurbishment works

For the door locations, please see the floor plans attached along with this building record.

Door Numbers:



Second Floor Internal Doors



Internal Photo D201i

Photo Location - Bedroom 6 - Door Number **D201**- See floor plans for location

Located with 1750's section of the building

Door leaf - Presumed non original - Average condition

Frame and Architrave - Presumed non original - Average condition

Glass - None

Proposed works:

- To enable a new ensuite bathroom and greater amenity for the users the existing opening is to be converted into a sliding leaf pocket door. See proposed plans 001158 _ **112**

Second Floor Internal Doors



Internal Photo D202i

Photo Location - Landing - Door Number **D202**- See floor plans for location

Located with 1750's section of the building

Door leaf - Presumed non original - Good condition

Frame and Architrave - Presumed original - Good condition

Glass - None

Proposed works:

- To enable a new ensuite bathroom and greater amenity for the users the existing opening is to filled. See proposed plans 001 158 _ **112**

19th of March 2021.

Second Floor Internal Doors



Internal Photo D203i

Photo Location - Landing - Door Number **D203**- See floor plans for location

Located with 1750's section of the building

Door leaf - Presumed non original - Average condition

Frame and Architrave - Presumed non original - Average condition

Glass - None

Proposed works:

- To enable a new ensuite bathroom and greater amenity for the users the existing opening is to filled. See proposed plans 001158 _ **112**

Second Floor Internal Doors



Internal Photo D204i

Photo Location - Landing - Door Number **D204**- See floor plans for location

Located with 1750's section of the building

Door leaf - Presumed non original - Average condition

Frame and Architrave - Presumed non original - Average condition

Glass - None

Proposed works:

- To enable a new ensuite bathroom and greater amenity for the users the existing opening is to be filled. See proposed plans 001 158 _ **112**

Second Floor Internal Doors



Internal Photo D205i

Photo Location - Landing - Door Number **D205**- See floor plans for location

Located with 1750's section of the building

Door leaf - Presumed non original - Average condition

Frame and Architrave - Presumed non original - Average condition

Glass - None

Proposed works:

- To enable a new ensuite bathroom and greater amenity for the users the existing door and frame is to be replaced. See proposed plans 001 158 _ **112**

19th of March 2021.