

Building Recording - Ground Floor


External and Internal Doors

Showing existing photos, noted location, frame condition, leaf condition and proposed refurbishment works

The doors within the building are predominantly non original or have been re positioned. The 1840's section the building has also had walls and door way re positioned and replaced. It is generally aimed to retain all doors where possible, but where doors are to be removed it is proposed to re use and re position the frame and architrave.

For the door locations, please see the floor plans attached along with this building record.

Door Numbers:



Ground Floor External and Internal Doors



Internal Photo ED001E

Photo Location - External South - Door Number **ED001** - See floor plans for location

Located with 1850's section of the building

Door leaf - Presumed original - Good condition

Frame and Architrave - Presumed original - Good condition

Glass - Arched glass over - Presumed original - Good condition

Proposed works:

- Refurbish and repaint, retain original ironmongery
additional security locks to be added

19th of March 2021.

Ground Floor External and Internal Doors



External Photo ED002E

Photo Location - External West - Door Number **ED002** - See floor plans for location

Located with 1750's section of the building

Door leaf - Presumed original - Good condition

Frame and Architrave - Presumed original - Good condition

Glass - Presumed non original

Proposed works:

- Refurbish and repaint, retain original ironmongery

Ground Floor External and Internal Doors



External Photo ED003E

Internal Photo ED003i

Photo Location - External West - Door Number **ED003** - See floor plans for location

Located with 1750's section of the building

Door leaf - Presumed original - Good condition

Frame and Architrave - Presumed original - Good condition

Glass - None

Proposed works:

- Refurbish and repaint, retain original ironmongery
additional security locks to be added

Ground Floor External and Internal Doors



External Photo ED004E

Photo Location - External West - Door Number **ED004** - See floor plans for location

Located with 1840's section of the building

Door leaf - Presumed original - Good condition

Frame and Architrave - Presumed original - Good condition

Glass - Presumed non original

Proposed works:

- Refurbish and repaint

Ground Floor External and Internal Doors



External Photo ED004E

Photo Location - External East - Door Number **ED005** - See floor plans for location

Located with 1750's section of the building

Door leaf - Presumed original - Good condition

Frame and Architrave - Presumed original - Good condition

Glass - None

Proposed works:

- Refurbish and repaint

Ground Floor External and Internal Doors



External Photo ED006E



Internal Photo ED006i

Photo Location - External East - Door Number **ED006** - See floor plans for location

Located with 1840's section of the building

Door leaf - Presumed non original - Good condition

Frame and Architrave - Presumed non original - Good condition

Glass - Central pane presumed non original - Good condition
- Smaller panes presumed non original - Good condition

Proposed works:

- Refurbish and repaint

Ground Floor External and Internal Doors



External Photo ED007E

Photo Location - External South - Door Number **ED007** - See floor plans for location

Located with 1990's section of the building

Door leaf - Presumed original - Average condition

Frame and Architrave - Presumed original - Average condition

Glass - None

Proposed works:

- Refurbish and repaint

Ground Floor External and Internal Doors



External Photo ED008E



External Photo ED008i

Photo Location - External West - Door Number **ED008** - See floor plans for location

Located with 1990's section of the building

Door leaf - Presumed original - Good condition

Frame and Architrave - Presumed original - Good condition

Glass - Presumed original - Good condition

Proposed works:

- Refurbish

Ground Floor External and Internal Doors



External Photo ED009E

External Photo ED009i

Photo Location - External West - Door Number **ED009** - See floor plans for location

Located with 1840's section of the building

Door leaf - Presumed non original - Poor condition

Frame and Architrave - Presumed non original - Poor condition

Glass - Presumed non original - Poor condition

Proposed works:

- Replaced

Ground Floor External and Internal Doors



Internal Photo D001i

Photo Location - Hall - Door Number D001 - See floor plans for location

Located with 1750's section of the building

Door leaf - Presumed original - Good condition

Frame and Architrave - Presumed original - Good condition

Glass - None

Proposed works:

- Refurbish and repaint.**

Ground Floor External and Internal Doors



Internal Photo D002i

Photo Location - Lounge - Door Number **D002** - See floor plans for location

Located with 1750's section of the building

Door leaf - Presumed original - Good condition (currently being restored)

Frame and Architrave - Presumed original - Good condition

Glass - None

Proposed works:

- Refurbish and repaint.
- Fire officer's comments on the proposed fire strategy is to be taken into account. It is aimed to retain the door and provide the required fire rating with intumescent frame seals.

Ground Floor External and Internal Doors



Internal Photo D003i

Photo Location - Dining Room - Door Number **D003** - See floor plans for location

Located with 1750's section of the building

Door leaf - Presumed original - Good condition missing timber pane

Frame and Architrave - Presumed original - Good condition

Glass - Non original to be removed

Proposed works:

- Refurbish and repaint, replace timber pane

Ground Floor External and Internal Doors



Internal Photo D004i

Photo Location - Cupboard in hall - Door Number **D004** - See floor plans for location

Located with 1750's section of the building

Door leaf - Presumed non original - Average condition

Frame and Architrave - Presumed non original - Average condition

Glass - None

Proposed works:

- Refurbish and repaint

Ground Floor External and Internal Doors



Internal Photo D005i

Photo Location - Staff Room - Door Number **D005** - See floor plans for location

Located with 1750's section of the building

Door leaf - Presumed original - Good condition

Frame and Architrave - Presumed original - Good condition

Glass - None

Proposed works:

- Refurbish and repaint

Ground Floor External and Internal Doors



Internal Photo D006i

Photo Location - Office - Door Number **D006** - See floor plans for location

Located with 1840's section of the building

Door leaf - Presumed non original - Good condition

Frame and Architrave - Presumed original - Good condition

Glass - None

Proposed works:

- Replace door leaf with new matching original doors, Refurbish and repaint frame

19th of March 2021.

Ground Floor External and Internal Doors



Internal Photo D007i

Photo Location - Entrance Hall - Door Number **D007** - See floor plans for location

Located with 1840's section of the building

Door leaf - Presumed original - Good condition

Frame and Architrave - Presumed original - Good condition

Glass - None

Proposed works:

- Refurbish and repaint frame

Ground Floor External and Internal Doors



Internal Photo D008i

Photo Location - Entrance Hall - Door Number **D008** - See floor plans for location

Located with 1840's section of the building

Door leaf - Presumed original - Good condition

Frame and Architrave - Presumed original - Good condition

Glass - Non original safety glass

Proposed works:

· Refurbish and repaint frame, to be consulted with the fire officer as an alternative first floor external fire escape is to be reinstated, this door can be retained with out replacement.

Ground Floor External and Internal Doors



Internal Photo D009i

Photo Location - Store - Door Number **D009** - See floor plans for location

Located with 1840's section of the building

Door leaf - Presumed original - Good condition

Frame and Architrave - Presumed original - Good condition

Glass - None

Proposed works:

- Refurbish and repaint frame

Ground Floor External and Internal Doors



Internal Photo D010i

Photo Location - Kitchen - Door Number **D010** - See floor plans for location

Located with 1840's section of the building

Door leaf - Presumed original - Good condition

Frame and Architrave - Presumed original - Good condition

Glass - Non original safety glass

Proposed works:

- Replace glass with new clear pane, Refurbish and repaint frame

19th of March 2021.

Ground Floor External and Internal Doors



Internal Photo D011i

Photo Location - Kitchen - Door Number **D011** - See floor plans for location

Located with 1840's section of the building

Door leaf - Presumed non original - Good condition

Frame and Architrave - Presumed original - Good condition

Glass - None

Proposed works:

- Refurbish and repaint frame

19th of March 2021.