


Existing Side (North) Elevation

## EXISTING MATERIALS

Roof:-	Cement fibre slate roof blue-black colour. Matching colour angular ridge tiles.	
Walls:-	Smooth render with paint finish or self coloured silicone render. Stained timber horizontal weatherboarding.	
RW Goods:-	Half round gutters and circular down pipes in black pvc-U Mat black woodgrain fascia & soffit boards.	
Doors:-	Colour-coated thermally broken aluminium frames. Painted and stained timber door & side screens.	
Windows:	- Colour-coated aluminium frames. Tinted double glazed units. Painted timber casements.	



## Existing Side (South) Elevation/Section

11 650

Buckle Chamberlain Partnership Ltd. Architects & Architectural Technologists. Mill House, Llancayo Court, Llancayo, Usk, Monmouthshire			
NP15 1HY	Email: end	uiries@bucklechamberlain.co.uk	
Client Mr & Mrs C. Pritchard.			
Project Proposed Alterations At Great House Farm Gwehelog, USK NP15 1RJ			
Drawing Existing Ground Floor Plan, Section & Elevations.			
Date Dec	: 2020	<sup>Scale</sup> 1:100 @ A1	
Drawn by	JSS	Drawing No	
Checked by	•	1562[PL]02 .	
Revision	Planning	·····	

scale in metres 1:100