



Elevation of the re-modelled building



Both side elevations of the re-modelled building



Interior of the building identifying the boxing in of the metal frame of the original glasshouse structure



An ivy plant grown in the ground in the original glass house structure; the ivy is seen still climbing the exposed portion of the metal frame