Mill End House - Outbuilding Replacement

Document 2


There is a large oak tree on our boundary that is close to the current outbuilding. Due to the current outbuilding being extremely old, rotting in places with an asbestos roof, we took the decision to employ a professional tree surgeon company to do a health check on this Oak tree earlier this year (2021). This was because we were worried about the current old outbuilding's roofing material being impacted and therefore being a threat to the immediate environment and the humans and animals etc in our surrounding area. The tree surgeon company pruned this tree considerably and made this tree safe for another 60-100 years. The location of the tree has been shown on a copy of the attached 'ReQuestaPlan' document for reference.

Mill End House, Durley

Document 2









Plan Produced for: Outbuilding Replacement

Date Produced: 07 Jun 2021

Plan Reference Number: TQRQM21158152102941

Scale: 1:1250 @ A4