



Existing Boundary Wall

Top section of round arch lintel collapsed due to ground movement

Proposed Repair

Clean off and reuse as many of the old bricks as possible.

Only suitable sourced replacement bricks to match existing to be used where needed.

Bricks to be bonded with lime mortar

Some crack repairs and repointing required to adjacent section of the boundary wall

There are no proposed significant changes to the existing appearance of the property. We will re-use the existing materials to rebuild the damaged section of the wall and the only unavoidable intervention will be to use some additional locally sourced bricks, which may be required to replace the damaged sections.

GENERAL NOTES

1. Dimensions are in millimetres unless stated otherwise.
2. Levels are in meters relative to project
3. Dimensions govern.
4. All dimensions to be verified on site before proceeding.
5. All discrepancies to be notified in writing to PAS Surveying
6. To be read in conjunction with all relevant engineers and specialists' drawings and specifications.

PAS SURVEYING

T: 07789 995118

E: phil.sciberras@passurveying.com

CLIENT

Sarah Wright
Brook Farmhouse
Colchester Main Road
Alresford
Essex CO7 8AP

TITLE

Existing & Proposed
Elevation Drawing

Scale – NTS

Number
2106WR

Revision
A