

CHARE HEAD FARMHOUSE PHOTOGRAPH SCHEDULE



1. *Rear elevation*



2. *Front elevation*



3. *Part of gable elevation above the front wall*



4. *Loose stonework to the top section of the gable wall*



5. *Defective stone lintel above the window opening on the rear elevation*



6. *Timber roof structure*



7. *Cobble floor with clay drainage channel*



8. *Defective timber beam above the large opening on the rear elevation*