

Basement windows prior to commencement of works showing blocking up of original windows using non-original materials (breeze blocks vs original bungaroosh construction). Both window openings were found to be of identical construction




Regency Society photograph of property showing original windows and pavement details as found at:

[http://regencysociety-jamesgray.com/volume29/source/jg\\_29\\_006.htm](http://regencysociety-jamesgray.com/volume29/source/jg_29_006.htm)



High-resolution image provided by  
Regency Society



Original window opening following removal of breeze blocks. Tiles were found to be modern industrial tiles.

