

**Pictures of the original barn**

**External**



**West elevation (facing north)**



**North & west elevations (facing south-east)**



**West elevation**




**Example of localised area requiring repointing on west elevation**






**North elevation**



**Example of cracking to the north elevation**



**Internal**



**Facing north**



**Example of crack to west elevation**





**Facing south**



**Example of cracking to partition wall**

**1980s Barn**



**Example of damaged roof sheets**



**Example of corroded gutters**