



Damage to shutters (leaf adjacent to the wall), panelling, architrave, dado and skirting both within and to either side of the bay window



Ceiling fallen - fruiting bodies visible on ceiling around fallen area, on laths to central infill and on timbers



Floorboards damaged to Western side of the room near the bay window

Ceiling rose becoming loose



Ceiling plan shown dotted

Rev A. 30.05.18. Notes and radiators added  
Rev B 18.07.08. notes added

Please note that due to access limitations there have had to be some assumptions made on thickness of external walls etc

**EMBLETON TOWER  
EMBLETON  
ALNWICK**

**PLAN OF DINING ROOM  
AS EXISTING**

Scales 1:50

Date Sept 2017

BR

*Spence and Dower* LLP,  
**Chartered Architects**  
**25 Main Street**  
**Ponteland**  
**Newcastle upon Tyne NE20 9NH**  
**Tel: (01661) 820071**  
**Fax: (01661) 823788**  
**architects@spenceanddower.co.uk**

All dimensions should be checked on site.  
Do not scale from this drawing

© Spence and Dower LLP

M631 / 01

Rev.  
B