


GENERAL NOTES:

1. ALL LEVELS, DIMENSIONS AND DETAILS ARE INDICATIVE AND APPROXIMATE ONLY TO BE CONFIRMED BY THE CONTRACTOR PRIOR TO THE COMMENCEMENT OF CONSTRUCTION OR FABRICATION.
2. ALL SETTING OUT INFORMATION IS TO BE TAKEN FROM THE ARCHITECTS INFORMATION.
3. THIS DRAWING IS TO BE READ IN CONJUNCTION WITH ALL OTHER RELEVANT DRAWINGS, SPECIFICATIONS & INFORMATION.
4. THE CONTRACTOR IS RESPONSIBLE FOR THE DESIGN, INSTALLATION AND MAINTENANCE OF ALL NECESSARY TEMPORARY WORKS TO ENSURE THE STRENGTH AND STABILITY OF THE BUILDING THROUGHOUT THE COURSE OF THE WORKS.
5. THE EXISTING STRUCTURAL INFORMATION SHOWN ON THESE DRAWINGS IS BASED ON VISUAL INSPECTION OF THE BUILDING AND UPON LIMITED OPENING UP WORKS. ALL DETAILS OF THE EXISTING CONSTRUCTION ARE SUBJECT TO CONFIRMATION BY THE CONTRACTOR DURING THE WORKS ON SITE. NO MATERIALS ARE TO BE ORDERED UNTIL THE RELEVANT DETAILS AND CONDITIONS ARE CONFIRMED BY THE CONTRACTOR ON SITE.



ROOF GA  
SCALE 1:50

LEGEND:

- Denotes existing masonry
- Denotes proposed masonry
- Denotes proposed concrete
- Denotes demolition
- Denotes structural crack
- Denotes 6mm Hell-bars
- Denotes proposed steel
- Denotes proposed timber
- Denotes water ingress

Instruction for masonry repair/ strengthening:

- # Crack repair using 2No. 6mm dia. helical bars inserted at every 2nd course of stonework or 4th course of brickwork (approx 300mm ctrs.). Allow for 1000mm long bars at full height of crack.
- \* Cross-wall tying with min. 1000mm long 10mm dia. Helibar 'CemTie' ties inserted at every 2nd course of stonework or 4th course of brickwork (approx. 300mm ctrs.). Allow for 1000mm long bars at full height of crack.

Instruction for timber repair:

- Denotes portion of timber elements where **less than 25%** of the cross section is affected by biological degradation which needs to be **cleaned and checked** in high detail. Contact SE (JCC) if degradation is more than 20mm deep.
- Denotes portion of timber elements where **more than 25%** of the cross section is affected by biological degradation which needs to be **replaced** using typical splice details.

Allow for 30% of all rafter and purlin ends to be repaired/replaced using typical splice details. All existing timber face cut on site to be preservative treated. All new timber to be preservative treated.

P01	First Issue	BB/AA	AA/WH	16/07/21
-----	-------------	-------	-------	----------

Rev	Description	Drawn	Check'd	Date
-----	-------------	-------	---------	------

Drawing Status:  
**PRELIMINARY**  
Drawing issued for comment

T. (0191) 491 4684  
E. enquiries@jc-consulting.net  
www.jc-consulting.net

Unit 16, The Stottle Shed  
Bakers Yard, Christon Road  
Goaforth, Newcastle upon Tyne  
NE3 1XD

Civil Engineering  
Structural Engineering  
Geo-Environmental Engineering

© JC CONSULTING LTD.

Client:  
**RABY ESTATE**

Project:  
**THE RISE - RABY CASTLE**

Drawing Title:  
**08. GAS HOUSE  
ROOF GA**

Scale: AS SHOWN	Drawn: AA	Checked: KH	Date: 16/07/21
Job Number: JCC20 - 235	Drawing Number: S - 08 - 220	Rev: P01	Size: A1