

4. Photo showing bathroom and stairway with wallpaper removed using a hand scraper and damp cloth. No damage to underlying fabric and no remedial action required. Wall beneath is lime plaster and some sections of gypsum plaster. Location on Floorplan C and D.

Stairway wallpaper removed showing limewashed lime plaster beneath and also sections of gypsum plastered wall/ceiling. All in good condition and no repairs required. Location C.



Bathroom wallpaper removed showing limewashed lime plaster and areas of gypsum plaster beneath. All in good condition and no repairs required. Location D.



Photo showing Parlour WC before with fibreboards lining the walls and subsequent photo of exposed walls with fibreboards and boxing removed. No damage to underlying fabric, walls in good condition, composed of lime, bare brick and some areas of gypsum plaster, no remedial action required. Location on Floorplan E.



Photo showing Downstairs Bathroom/Service end before with fibreboards lining the walls and subsequent photo of exposed walls with fibreboards removed. No damage to underlying fabric, walls in good condition, composed of lime and no remedial action required. Location on Floorplan F.



Photos showing areas of concrete render to be removed and photos of render removed. Location on Floorplan G, H and I. Most existing Riven Chestnut laths in good condition, brickwork plinth in good condition.

