

ELEVATION NORTH SCALE 1:100
The Velux skylight
Roof Windows.

Drawing No 3

Post Room
F.O.D.D.C
10/10/2020

Entire roof surface
to be replaced with
natural slates,

lead flashing.

see
for
grid

APPROX
Door
to be
rated
intumes

Existing damaged cement render to
South gable to be replaced with lime mortar
to
back block up existing doorway, render
to match existing
fill new owl window to match adjoining
panel window.

North.
unless otherwise noted, all windows shown on
these elevations are existing

new window on North Elevation
painted to match existing

RENDER (to walls in blocked up openings)
2 coats (min 13mm) 1:3 cement: sand Render
finished to match adjoining work. Form both
mouth in render over door + windows and
at DPC level, all onto gable ms render steps