

APPENDIX A

Site photographs



Photograph 1

Description: Site A: proposed motocross reception and parking area

Date: 28/04/2021

Location: View from current access road – looking to the east



Photograph 2

Description: Site A: proposed motocross reception and parking area

Date: 28/04/2021

Location: View from central site area – looking to the east



Photograph 3

Description: Site A: proposed motocross reception and parking area

Date: 28/04/2021

Location: View from western part of the site – looking to the east



Photograph 4

Description: Site A: proposed motocross reception and parking area

Date: 28/04/2021

Location: View from western part of the site – looking to the west



Photograph 5

Description: Site A: artificial bank resulting from previous groundworks

Date: 28/04/2021

Location: View from central-western part of the site – looking to the south



Photograph 6

Description: Site A: drainage rills within the artificial bank

Date: 28/04/2021

Location: South-western part of Site A



Photograph 7

Description: Site A: surface cracks within clayey soils

Date: 28/04/2021

Location: South-western part of Site A



Photograph 8

Description: Site A: sloping ground leading down to Dulas Brook

Date: 28/04/2021

Location: Northern boundary of Site A – looking to the north-west



Photograph 9

Description: Site A: Dulas Brook river corridor

Date: 28/04/2021

Location: Northern boundary of Site A – looking to the east



Photograph 10

Description: Trial pit TP01

Date: 28/04/2021

Location: North western part of Site A



Photograph 11 **Description:** Spoil removed from trial pit TP01
 Date: 28/04/2021
 Location: North western part of Site A



Photograph 12 **Description:** Spoil removed from trial pit TP01
 Date: 28/04/2021
 Location: North western part of Site A



Photograph 13 **Description:** Water level monitoring at trial pit TP01 (start of test)
Date: 28/04/2021
Location: North western part of Site A



Photograph 14 **Description:** Water level monitoring at trial pit TP01 (end of test)
Date: 28/04/2021
Location: North western part of Site A



Photograph 15

Description: Trial pit TP02

Date: 28/04/2021

Location: North western part of Site A



Photograph 16

Description: Spoil removed from trial pit TP02

Date: 28/04/2021

Location: North western part of Site A



Photograph 17 **Description:** Inundation of trial pit TP02 (start of test)
 Date: 28/04/2021
 Location: North western part of Site A



Photograph 18 **Description:** Trial pit TP02 (end of test)
 Date: 28/04/2021
 Location: North western part of Site A



Photograph 19

Description: Hand pit HP01

Date: 28/04/2021

Location: Lower terraced area in the central-western part of Site A



Photograph 20

Description: Hand pit HP01 (start of test)

Date: 28/04/2021

Location: Lower terraced area in the central-western part of Site A



Photograph 21

Description: Hand pit HP01 – increase in water levels at end of test

Date: 28/04/2021

Location: Lower terraced area in the central-western part of Site A



Photograph 22

Description: Hand pit HP02

Date: 28/04/2021

Location: Upper terraced area in the central-western part of Site A



Photograph 23

Description: Hand pit HP02 (start of test)

Date: 28/04/2021

Location: Upper terraced area in the central-western part of Site A



Photograph 24

Description: Hand pit HP02 (end of test)

Date: 28/04/2021

Location: Upper terraced area in the central-western part of Site A



Photograph 25

Description: Hand pit HP03

Date: 28/04/2021

Location: Sloping land to the south of the current access



Photograph 26

Description: Hand pit HP03 (end of test)

Date: 28/04/2021

Location: Sloping land to the south of the current access



Photograph 27

Description: Hand pit HP04

Date: 28/04/2021

Location: Sloping land to the south of the current access



Photograph 28

Description: Hand pit HP04 (start of test)

Date: 28/04/2021

Location: Sloping land to the south of the current access



Photograph 29

Description: Hand pit HP04 (end of test)

Date: 28/04/2021

Location: Sloping land to the south of the current access



Photograph 30

Description: Hand pit HP05

Date: 28/04/2021

Location: Sloping land to the south of the current access



Photograph 31

Description: Hand pit HP05 (start of test)

Date: 28/04/2021

Location: Sloping land to the south of the current access



Photograph 32

Description: Hand pit HP05 (midway through test)

Date: 28/04/2021

Location: Sloping land to the south of the current access



Photograph 33

Description: Hand pit HP05 (end of test)

Date: 28/04/2021

Location: Sloping land to the south of the current access



Photograph 34

Description: Site B: area of proposed log cabin development

Date: 28/04/2021

Location: View from central part of site – looking to the south



Photograph 35

Description: Site B: area of proposed log cabin development

Date: 28/04/2021

Location: View from central part of site – looking to the north



Photograph 36

Description: Site B: area of proposed log cabin development

Date: 28/04/2021

Location: View from Site B looking to the west



Photograph 37

Description: Trial pit TP03

Date: 28/04/2021

Location: Land directly to the north-west of Site B



Photograph 38

Description: Trial pit TP03

Date: 28/04/2021

Location: Land directly to the north-west of Site B



Photograph 39

Description: Clay deposits removed from trial pit TP03

Date: 28/04/2021

Location: Land directly to the north-west of Site B



Photograph 40

Description: Trial pit TP04

Date: 28/04/2021

Location: Western-central part of Site B