



North Elevation (grid A)

- 1 Missing stud
- 2 wall plate degraded (or missing)
- 3 Split at top of post
- 4 post severe decay
- 5 section of post severe decay
- 6 large hole to front
- 7 large hole to u/s beam
- 8 face severe decay
- 9 large hole to rear
- 10 loss of section and connection
- 11 loss of connection
- 12 loss of section
- 13 missing brace
- 14 added brace
- 15 beam severe decay
- 16 missing rafter
- 17 defective purlin connection

**Note.**  
 1.0 General  
 1.1 This drawing is to be read in conjunction with all relevant Project drawings together with the Project Specification  
 1.2 Do not scale off this drawing, work to figured dimensions only.  
 1.3 Any Discrepancies noted between drawn information are to be reported promptly to the Contract Administrator.

© Cooper & Withycombe  
 These drawings are not to be copied or distributed to third parties without the written consent of Cooper & Withycombe Ltd.

CLIENT <b>Candida Baker</b>			<b>Cooper &amp; Withycombe</b> CONSULTING ENGINEERS <small>Norwich House 14-16 North Street Guildford Surrey, GU1 4AF</small> <small>tel 01483 457373 Fax 01483 566118</small>		
PROJECT <b>Dickhurst Farm</b> <b>Petworth Rd.Chiddingfold,Surrey,</b> <b>GU27 8BG</b>			ARCHITECT <b>Stedman Blower Architects</b>		
TITLE <b>Frame Defects to</b> <b>North Elevation , grid A</b>			DWG. STATUS PRELIMINARY <input checked="" type="radio"/> TENDER CONSTRUCTION RECORD		
DRAWN BY <b>BFS</b> DATE <b>jan 22</b>		CHECKED BY <b>BA</b> DATE <b>jan 22</b>		APPROVED BY DATE	
BASE DRAWING SCALE <b>1: 50 @ A3</b>			SCHEDULE SHEETS		
PROJECT No <b>21-2152</b>		DRAWING No. <b>05</b>		REV <b>-</b>	