


Do not scale off this drawing — All dimensions and setting out to be verified on site. If in doubt contact the originator for clarification.

This drawing is the property of FRAMEWORK. Copyright is reserved by them and the drawing is issued on the condition that it is not copied, reproduced, retained or disclosed to any unauthorised person, either wholly or in part without the consent in writing of FRAMEWORK

Appendix 1: BS5837 Tree Schedule BS 5837 2012: Cascade Chart for Quality Key Measurements Age - Class YNG-MAT-Young Mature < = less than A - High Young Mature SM - Semi-mature Mat - Mature U - Trees of negligible significance Est Yrs - estimate of years 1 = mainly arboricultural value 2 = mainly landscape values 3 = mainly cultural values.

RPA = Root protection area (equivalent to a circle with a radius 12 x the stem diameter for single stem trees and 10 x the basal diameter for trees with more than one stem arising below 1.5m above ground level).

Tree No	Species	Ht (m)	Stem Diam mm@ 1.5m	Canopy Spread (m)	Height of Crown Clearance	Age Class	Est	Overall Condition	Structural Condition	Recommendations	BS 5837 Category	RPA Radius (m)
T1	Willow Salix alba Tristis	8	280	N-3 S-4 E-2 W-4	2	SM	20	F	Single trunk leaning slightly east. Pollarded pendulous crown with a cable through the south east side of the crown. Negligible roost potential. No structural faults visible from ground level	None. This tree will require seasonal pollarding to protect the overhead cable and reduce impact on the adjacent road if it is retained.	B2	3.3
T2	Willow Salix alba Tristis	8	455	N-4 S-5 E-4 W-4	4	М	20	G	Single trunk supporting a balanced pendulous canopy pollarded at 6magl. Negligible roost potential. No structural faults visible from ground level	None. This tree will require seasonal pollarding to protect the overhead cable and reduce impact on the adjacent road if it is retained.	B2	5.4
ТЗ	Sycamore Acer pseudoplatanus	20	785	N-3 S-8 E-7 W-5	4	М	20	F	Single trunk with ivy cover to 10magl. Basal regeneration present with an irregular crown extending south east over electricity cables. Low roost potential due to ivy. No structural faults visible from ground level but canopy reduction close to cables will be required in the future.	The crown and RPA of this tree will need to be protected on the eastern side.	B1	9.4
T4	Sequoia Sequoia sempervirons	20	830	N-2 S-3 E-3 W-2	>5	М	20	G	Single trunk with ivy cover supporting a high lightly branching crown. Low roost potential due to ivy cover. No structural faults visible from ground level	The RPA and crown of this tree will need to be protected on the eastern side.	B1	9.9
T5	False Acacia Robinia pseudoacacia	11	335	N-3 S-4 E-5 W-4	5	SM	10	F	Single trunk supporting an irregular crown extending east over the adjacent garage roof. Minor dead wood throughout. Growing out of base of fence. Negligible roost potential. No structural faults visible from ground level but potential damage to fence as this matures.	None. It may be prudent to consider removing this tree as the crown extend to the adjacent roof.	C2	4.0
G1	Hawthorn Crataegus monogyna	5	<150	N-3 S-3 E-3 W-3	0	Y	10	G	Line of young hawthorn with the side trimmed but not topped. Negligible roost potential. No structural faults visible from ground level	This hedgerow will have to continue to be maintained through seasonal trimming.	C2	1.8



3 MARINE STUDIOS, BURTON LANE END, BURTON WATERS, LINCOLN, LN1 2UA T 01522 535383 E Info@frameworklincoln.co.uk W frameworkarchitects.co.uk