



All Sectors: Investigate for loose sections of face-work

Plinth strip, Sector c1, d1, e1, f1, g1, h1

Pointing is worn back and existing aggregate to mortar too fine. Cut back pointing to firm substrate and re-point taking special care around pebbles used in this layer.

Re-bed some 7+ missing flints plus those disturbed by work in this area.

Point around fixings to downpipes.

point joints to chamfered plinth course.

Tamp back final pointing finish to expose flint edges.

Apply shelter-coat to 3 badly weathered ventilation stones.

Sector e3 new bath-stone indent to quoin block
full height of block on side face

Purpose of issue	
Project :	Church House, Wood Street ENS
Drawing Title:	Photographic Survey
Drawing No:	2964/ H /P4
Revision:	
Scale:	Date: June 2021
UPCHURCH ASSOCIATES	C/O 58 The Drive, High Barnet, Herts ENS 4JQ. www.upchurch-architects.com