



3.47 +

Valley Farm plan- location of Vine room ceiling to be repaired

Red line indicates ceilings to be repaired and replastered using traditional methods .

3.34

+

REV    DATE

