



EXISTING TRACTOR LODGE HAS A CONCRETE FLOOR ON A PLASTIC DPM. STONEMWORK SHOWS STRUCTURAL CRACKS TO BACK WALL. ROOF BOWING AND SHOWING CORROSION TO METAL CORRUGATED SHEET. TIMBER COLUMNS CRACKED AND WITH EVIDENCE OF ROTTING AT GROUND LEVEL.





EXISTING



STRIPP

DESIGN

3

07513 782517