



Plate 1: View of the barn from the South East.



Plate 2: View of the barn from the South West.



Plate 3: View of the barn from the North West. Note the slope in ground level.



Plate 4: Internal view of the barn.



Plate 5: View of the barn roof. Note bent purlins, possibly tree branches or small trunks.



Plate 6: Typical roof rafters. Possibly tree branches or small trunks.



Plate 7: Strengthening of original timber king post truss.



Plate 8: Insect boring attack of timber roof truss.



Plate 9: Slab within the barn.



Plate 10: Trial hole 1.



Plate 7: Trial hole 2.



Plate 8: Trial hole 3.



Plate 7: Trial hole 4.



Plate 8: Trial hole 5..