

## Moor Farm 1

Talaton

0604

19.05.2022



This image shows the southern and eastern sides of the stable cum barn, which the applicant proposes to convert to provide a dwelling for herself, together with the addition of an extension in part of the yardage that surrounds the building

0605

19.05.2022



The eastern side of the stable to the left and the barn to the right, but with no partition between both parts, is shown in this image. A conversion would also require a small extension within the area shown on this side of the building. Note the eight ventilation openings in the rear wall

## Moor Farm 2

Talaton

0615

19.05.2022



The western side of the stable/barn is shown in this image, with the barn part behind the gate and the green screen

0616

19.05.2022



The western side of the stable/barn is shown in this image, with the barn part behind the gate and the green screen. A corrugated plastic panel set into the roof provides an abundance of natural light in the barn part. Both sides of the single floor area building are very well ventilated as well as well lit

## Moor Farm 3

Talaton

0607

19.05.2022



This image was taken inside the barn area to the left and the stable part to the right, shows how well-lit and well ventilated the building is

0608

19.05.2022



This image was taken to show the barn part of the building. It shows how well-lit and well ventilated the building is

## Moor Farm 4

Talaton

0612

19.05.2022



An old blackbird's nest was built in one of the blockwork support pillars, but the bird has not returned to re-use the nest during the current nesting season

0613

19.05.2022



The join between the roof-support beam that rests on the top of the brick-capped blockwork wall, and the corrugated metal roof covering, is festooned with cobwebs. That demonstrates a lack of disturbance by any flying animals