


<u>Notes</u>

 NEW CORRUGATED CEMENT ROOF TO MATCH MAIN BARNS.

2. POOL PLANT UNDER RAISED DECK.

- ATCH MAIN 3. NEW FLUE.
  - NEW OPENABLE ROOFLIGHT OVER STAIRCASE TO ALLOW LIGHT AND VIEW OF SKY INTO STAIRCASE CORE.
- 5. OPENABLE ROOF LIGHT TO BE FLUSH WITH NEW CORRUGATED ROOF. NEW ROOF LIGHTS TO REFLECT EXISTING ROOFLIGHT LOCATIONS.
- 6. NEW CORRUGATED CEMENT ROOF TO MATCH EXISTING.

REVISION:



## BRINKWORTH

PHONE +44 (0)20 7613 5341 INFO@BRINKWORTH.CO.UK WWW.BRINKWORTH.CO.UK 4-6 ELLSWORTH ST, LONDON E2 0AX

All drawings within this package are the copyright of Brinkworth. They may not be copied or disclosed to any third party for any purpose except as authorised in writing by Brinkworth.

Do not scale from these drawings. Figured dimensions only are to be used. All critical dimensions are to be checked on site before work proceeds. If in doubt ask.

All drawings are to be read in conjunction with all other relevant consultants and/or specialists drawings or documents.

Inconsistencies, errors and omissions found within or between Brinkworth documents (and also in relation to other consultants/specialists documents) are to be notified immediately to Brinkworth.

CLIENT R & D Lehtonen - Riley

JOB TGF Barn

TITLE Main Barn Proposed Roof Plan

JOB NO. 3979 DWG. NO. 3003

DRAWN BY WW CHECKED BY SC

DATE 08/22 REV

© COPYRIGHT BRINKWORTH

SCALE 1:100