

External / internal window schedule - Works to existing windows

Project Name:
The Annexe, Creswell Road, Cuckney

Reference:
20680

Issue date : 03.08.2022
Revision : P01

NOTE : ALL DIMENSIONS TAKEN FROM MEASURED SURVEY DRAWING REF: 1056-172_E ELEVATIONS SURVEY & SECTIONS ONLY. ALL DIMENSIONS TO BE CHECKED ON SITE PRIOR TO MANUFACTURE OF ANY REPLACEMENT WINDOWS

For window locations please refer to the following drawings :- 03011-Existing Elevations

Level	Reference	Structural Opening (mm)		Description	Dating from (approx)	Level of significance 1 = none/detrimental, 4 = high	Retained and repaired	Removed and disposed of	Secondary glazing required	Replacement window required	Condition Notes
		Appx. Width	Appx. Height								
Level 00 - Ground Floor	W-L0-018	1073	1387	Single-glazed timber vertical sliding sash window with glazing bars.	C20th	3	NO	YES	NO	YES	Fair condition. To be replaced with new like for like double glazed timber framed vertical sliding sash window.
Level 00 - Ground Floor	W-L0-019	1068	1216	Single-glazed timber vertical sliding sash window with glazing bars.	C20th	3	NO	YES	NO	YES	Fair condition although adjustment to mechanisms required. To be replaced with new like for like double glazed timber framed vertical sliding sash window.
Level 00 - Ground Floor	W-L0-020	1068	1110	Single-glazed timber horizontal sliding sash window with glazing bars	C18th	4	NO	YES	NO	YES	Fair condition. Windows painted shut. To be replaced with new like for like double glazed timber framed horizontal sliding sash window.
Level 00 - Ground Floor	W-L0-021	TBC	TBC	Single glazed timber window with top opening light and glazing bars. Obscure glazing to bottom panes and mesh infill to top section.	C20th	1	NO	YES	NO	YES	Fair condition. To be replaced with new like for like double glazed timber framed casement window. No survey information drawn for this window.
Level 01 - First Floor	W-L1-005	803	993	Single-glazed timber horizontal sliding sash window with glazing bars	C18th	4	NO	YES	NO	YES	Fair condition. Windows appear painted shut and are inaccessible owing to double height volume. To be replaced with new like for like double glazed timber framed horizontal sliding sash window.
Level 01 - First Floor	W-L1-006	851	1025	Single-glazed timber horizontal sliding sash window with glazing bars	C18th	4	NO	YES	NO	YES	Fair condition with small signs of rotten timber to lower section. Windows painted shut. To be replaced with new like for like double glazed timber framed horizontal sliding sash window.
Level 01 - First Floor	W-L1-007	TBC	TBC	Single-glazed timber vertical sliding sash window with glazing bars	C20th	3	NO	YES	NO	YES	Fair condition. To be replaced with new like for like double glazed timber framed casement window. No survey information drawn for this window.