

## Appendix B Photo Log



No 1

Looking north from the site access road towards Wilmslow Old Road.



No 2

Looking south west towards the previous farming buildings, showing vegetation out-break and potential asbestos cement roofing.



No 3

Ad-hoc fly tipping against the eastern wall of the listed farm building.



No 4

Looking east into the central area of the farm buildings, showing construction debris and a mix of corrugated iron, plastic and asbestos cement roofing. Unidentifiable agricultural waste observed within the building structure.



No 5

Stockpile of unidentified waste on the north-eastern boundary of the listed farm house, looking north-west.



No 6

Stockpile of unidentified waste (No 5) looking south. Evidence of construction debris and larger fragments.



No 7 | Looking north from the listed farm house showing current land and vegetative state.



No 8 | Stockpile of unidentified waste on south west boundary of listed farm house. Material has been previously sorted, however evidence of broken tarmac and mixing is present. Grass mound is previously covered construction waste (No 10), looking west.



No 9 | Broken tarmac within the stockpile (No 8).



No 10 | Previously covered construction waste (No 8), looking east.



No 11

Numerous stockpiles of unidentified material, looking north east from No 8. Overhead powerlines present.



No 12

Numerous stockpiles of unidentified material, looking north from No 8. Overhead powerlines present.



No 13

South east behind the stockpile (No 8), potentially infilled pond / depression of unconsolidated and mixed material. Strong odour.



No 14

Access to the southern portion of the site from the listed farm house visible in the distance, looking north.





No 15

Looking south towards the southernmost boundary of the site. Land is predominantly undeveloped grass land.



No 16

Potentially infilled pond identified by differing vegetation within the southern portion of the site, looking south.



No 17

Access to the RVP Events Field from the Manchester Airport Viewing Park, looking north.



No 18

Potentially infilled pond / depression on the southern boundary of the RVP Event Field.



No 19 | RVP Events Field, looking north east.



No 20 | RVP Events Field, looking south.



No 21

Grassed mound covering potential previous waste on the western boundary of the RVP Event Field. Vegetation growing on the mound is different to surrounding vegetation.



No 22

Broken and discontinuous made ground and access road, looking east towards the listed farm building. Overhead powerlines present.



No 23 | Western portion of the site, looking south.



No 24 | Northern portion of the site, separated by two hedgerows, looking west.



No 25

Northern most portion of the site, looking north west towards the Cotteril Clough Brook boundary.



No 26

Previously abandoned industrial units and semi-permanent buildings to the west of the listed farm building, looking south west. Overhead powerlines present.

