



## Notes

- 1. Remove paint to window mullions and transoms to windows W39, W38 and W37
- 2. Generally tidy up glazing beads and remove excess paint to all glass
- 3. Once the lean roof structure is removed, check for damage repairs to existing brickwork and make good as necessary

## ML Mast light code 7962 by Astro Lighting

| Drojost: Th     | IE MALTINGS, WEYBOU  | DNE NODEC    | JI K VIDO       | 5 7QV             |                           |               | *************************************** |  |
|-----------------|----------------------|--------------|-----------------|-------------------|---------------------------|---------------|---|--|
| <u></u>         |                      | INIC, NONFO  | JLK INNZ        | 3731              |                           |               | ·                                       |  |
| Subject: E      | XTERNAL ELEVATION.   |              |                 |                   |                           |               | 5                                       |  |
| Scale: 1:       | 100. Date: May, 22.  | Project Ref: | TM.             | Drwg. No.:        | 236                       | Rev.:         |   |  |
| Architects:     | Big Brown Dog Limite | d Th         | e Old Po        | st Office, Brooks | side, Dalh                | am, Suffolk C | B8 8T                                   |  |
| T: 01638 500234 |                      | F: 01638     | F: 01638 500343 |                   | E: bigbrowndog@keme.co.uk |               |   |  |
| Original size   | e: A2                |              |                 |                   | © BIG BF                  | ROWN DOG L    | IMITE                                   |  |