

Burnthouse Farm – Samples of Existing Timber Frame & Plinth Wall Condition Following Exposure in Sitting Room (South & West Elevations)

Sitting Room – South Elevation



Sitting Room – South Elevation (note removed and stored wattle & daub panel in front of fireplace)



Sitting Room – West Elevation



Sitting Room – West Elevation



Sitting Room – West Elevation (note concrete & rubble infill)

