

the overhead power lines and will restict visibility. Additional tree planting will be provided to the rear to mitigate this removal.

New vehicular access- form new 4.5m wide - opening in existing wall, provide matching piers to each end

Refuse and recyclable

2°4

S

The front boundary wall is to be repaired in a suitable lime mortar, frost damaged bricks are to be replaced to match. Cement mortar is to be raked out and replaced with lime mortar.

Free draining surfacing to driveway/parking areas. No-dig construction to the RPA of the trees. Trees to be protected with Herras fencing during the course of the works

- Achievable visibility splay

-Y∉w

Sweet Chestrut

ഹ്

²

