




find attached picture 1 Winsor House - Barn Proposed.jpg - Side view of the barn showing existing roof with annotation to show proposed




Please find attached picture 2 Winsor House - Barn North Facing Proposed Picture showing barn roof from the upstairs of the property with annotation to show proposed change





Please find attached picture 3 Winsor House - Barn Internal Facing South Proposed.jpg - Picture of the inside of the barn with annotation to show proposed change





Winsor House Bow: Propose Internal Roof Structure, Facing North  
Application: 22/01749/LBC, Ref: PP-11293129

Corrugated roof to be replaced with new corrugated roof by Cladco  
Corrugated 13/3 PVC Plastic in Merlin Grey

Please find attached picture 4 Winsor House - Barn Internal Facing North Proposed.jpg - Picture of the inside of the barn with annotation to show proposed change