

Original clay lump walls shown thus  
 This section with pantile roof over  
 The application is for this section  
 to be removed as it has been  
 found to be structurally unstable  
 in relation to application ref  
 DC/21/06720.  
 The associated Structural  
 Engineering report to be read in  
 conjunction.

Timber frame and cladding walls shown  
 thus

MAIN HOUSE

KENNELS

WORKSHOP



KENNELS

CARTLIDGE

WORKSHOP

DO NOT SCALE DRAWINGS  
 the contractor is responsible  
 for checking and reporting any  
 discrepancy to the architect

REV: AMENDMENT: DATE:



**PHILIP MORPHY ARCHITECTS**

SHOP LANE, LITTLE GLEMHAM, IP13 0BD  
 0788 7841720 www.philipmorphy.co.uk 01728 746250

SIVA KENNELS, KENTON ROAD, MONK SOHAM, IP137EZ  
 WORKS IN ASSOCIATION WITH ANNEX CREATION7  
 P L A N S A S E X I S T I N G

PMA/582 1:50/A2. Oct21 AB302