

5) Replace missing or damaged soleplate.



2) Remove fletton brick infill. Replace with timber bracing.



1) Splice lower ends and rafters.



3) Replace rotten sole plate on raised position - Tenon fit extisting studs.

NO DIMENSIONS TO BE SCALED FROM THIS DRAWING

This document references the following file:-

Reference Name Revision

PC-XX-XX-M3-Designer-0001_5649

P01 First Issue

30/03/23 AO / MG

Client

Mr R. Eldridge

Project

Proposed Extension and Internal Alterations to The Pheasantry, Wattisham

Timber Frame Repairs

P01

5649 - 0512 Scale - unless otherwise stated

N/A

PRELIMINARY

BS 1192 Ref.

@ A3

PC-Designer-0512



The Old Steelyard Poplar Lane Sproughton Ipswich IP8 3HL t: 01473 689 532