

Photo II: Bathroom Window and In-fill Below



Photo 12: Old Doorframe Head in Bathroom Window Opening (showing poor window fitting)