Building Element Schedule for LBC: Internal Grassfield Hall

Apr-23

Basement

Basement Item no.	Room.	Item	LBC items for consent	Photo record
B1	Basement Stair	Floor: Solid stone flags.	Metal handrail and	riioto record
B1	Basement Stan	Ceiling: Plaster painted. Walls: Exposed stone	conservation works to lower levels. Doors. Radiators. All finishes. All fixtures and fittings. Basement level.	
B2	Basement Room 1 (store)	Floor: Solid stone flags. Ceiling: Plaster painted with two Victorian I beams covered in oak facing boards and straps. Walls: Exposed stone. Doors: Solid wood, new. Double glazed external doors, timber, painted.	Timber boarding to beams with straps and new external doors. All finishes. All fixtures and fittings.	
В3	Basement Room 2 (Female WC)	Floor: Solid stone with culvert repaired and restored. Ceiling: Plaster painted. Walls: Exposed stone. Temporary wc walls and doors. Window: One new double glazed window where the basement window had been blocked. Now reinstated. Doors: Timber panel and plastic to wcs.	New wc and associated fixings, screens and drainage. Reinstated new window. All finishes. All fixtures and fittings.	
B4	Basement Room 3 (Utility)	Floor: Solid stone flags. Ceiling: Exposed joists Walls: Exposed stone and painted brick plinths Doors: Solid timber Other: Location of boilers.	New timber door. All finishes. All fixtures and fittings.	

B5	(Vaulted store)	Floor: Solid stone flags/ Ceiling: vaulted arch stone. Walls: Exposed stone. Doors: Solid timber.	All finishes. All fixtures and fittings.	
----	-----------------	--	--	--

Ground Floor

Ground Fl	Ground Floor				
Item no.	Room.	Item		Photo record	
GF1	wc	Floor: Tile. Ceiling: Plaster painted. Walls: Plaster painted. Windows: 1 timber sash window. Doors: Timber panelled door to utility. Other: Sink and toilet plus cylinders.	All finishes. New door. All fixtures and fittings. New window.	N/A	
GF2	Utility	Floor: Tile. Ceiling: Plaster painted. Walls: Plaster painted. Windows. 1no. Timber sash window. Doors: 1no. 6 panel door to exterior. 1no. Panelled door to kitchen.	All finishes. New doors. New window. All fixtures and fittings.	N/A	
GF3	Kitchen	Floor: Tiles. Ceiling: Plaster painted. Walls: Plaster painted with cornice. Skirting. Windows: 6/6 single glazed sash window. Doors: Solid timber 4 panels. Cabinets: Modern timber and marble kitchen units. Fireplace: Aga in situ.	All finishes. New window, doors and re-opening of fire place. New kitchen units. All fixtures and fittings.		
GF4	Store	Floor: Tiles. Ceiling: Plaster painted. Walls: Plaster painted with cornice. Skirting. Doors: solid timber 4 panel door.	All finishes. New door. All fixtures and fittings.		

GF5	Rear Stair	Floor: Tiles Ceiling: Plaster painted. Walls: Plaster painted with cornice. Dado rails. Skirting. Stair: Modern timber staircase in traditional style. Windows: Timber sash window. Doors: 4 panel solid timber doors.	All finishes. Staircase. New window and doors. All fixtures and fittings.	
GF6	GF bedroom 1	Floor: Carpet. Ceiling: Plaster painted. Walls: Plaster painted with cornice. Doors: Timber double doors partially glazed leading to small outdoor yard.	All finishes. New double doors, window and door. All fixtures and fittings.	
GF7	GF bedroom en-suite	Floor: Tiles Ceiling: Plaster painted with partial faux ceiling. Walls: Tiled. Doors: 4 panel solid timber door. Sanitary fittings: Shower unit, wc and sink.	New shower room with all finishes. All fixtures and fittings.	
GF8	Conservatory	Floor: Concrete Ceiling: Exposed. Walls: Exposed blockwork. Windows: Large timber glazed in poor condition. Doors: Glazed doors.	All finishes, fixtures and fittings.	

GF9	Diner	Floor: Parquet flooring. Ceiling: Plaster painted. Walls: Plaster painted with cornice. Dado rail. Skirting. Blocked up doors to conservatory. Windows: 6/6 timber sash window. Doors: 6 panel solid timber door. Fireplace: New fireplace in historic opening.	All finishes. All fixtures and fittings. Fireplace. New window. New doors.	
GF10	GF Stair	Floor: Tiles to the floor. Ceiling: Plaster painted. Walls: Plaster painted with cornice. Dado rail. Skirting. Doors Stair: Timber staircase in a traditional, plain style.	Finishes, fixtures and fittings. New staircase. Doors. NOTE. This LBC application excludes the lower level glazed balustrade and consent is only sought for the timber balustrading to the first floor.	NAME OF THE PROPERTY OF THE PR
GF 11	Snug	Floor: Parquet timber floor. Ceiling: Plaster painted. Walls: Plaster painted with cornice. Dado rail. Skirting. Doors: 6 panel solid timber doors. Window. 1no. 6/6 single glazed sash window. Fireplace: New fireplace in original opening.	All finishes. Fixtures and fittings. New window. New doors. New fireplace.	
GF12	Hall Entrance	Floor: Tiles. Ceiling: Plaster painted. Walls: Double height. Plaster painted with ornate cornice. Dado rail. Skirting. Windows: 3 no 6/6 single glazed timber sash windows of which only 1 is visible from the outside. Doors: External refurbished pre-war wooden door.	LBC application for this space is only seeking consent for the fixtures and fittings and the 2 upper windows and the 1 blocked ground floor window. NOTE: The application excludes the future proposals for staircase and replacement of glass balustrade.	

GF13	Sitting Room	Floor: Parquet timber. Ceiling: Plaster painted. Walls: Plaster painted with ornate cornice which matches the meandros design of the new fireplace. Skirting. Doors: 6 panel solid timber door. Windows: 2no. 2/2 single glazed timber sash windows. 1no. 6/6 single glazed timber sash window. Fireplace: Reclaimed fireplace with Meandros pattern in original opening.		
GF14	Lobby	Floor: Tiled. New wall between lobby and dining hall. This wall replicates what was originally there but removed during the Victorian period. Ceiling: Painted plaster. Walls: Painted plaster with ornate cornice, dado rail, skirting. Doors: 6 panel solid timber doors to internal spaces. Original glazed timber double doors with espagnolette ironmongery and fanlight.	All fixture and fittings. All finishes. New doors.	
GF15	Dining Hall	Floor: Parquet wood Ceiling: Plaster painted. Walls: New wall reinstated. Painted plaster to all walls with panelled features. Doors: Opening blocked to the conservatory. 6 panel solid timber door. Windows: 2no. 2/2 single pane sash windows. Fireplace: Reclaimed fireplace.	All finishes. All fixtures and fittings. New windows and new doors. New fireplace.	

First Floor

Item no. Ro	oom.	Item		Photo record
-------------	------	------	--	--------------

FF1	FF Bedroom 1	Floor: Carpet. Ceiling: Plaster painted. Walls: Plaster painted with cornice. Skirting. Windows: 1no. Large timber single glazed bay window. Doors: 4 panel solid timber doors.	All finishes. All fixtures and fittings. New door.	
FF2	FF Bedroom 1 Ensuite	Floor: Tiles. Ceiling: Plaster painted. Walls: Plaster painted with half pannelling painted. Windows: 6/6 single glazed timber sash window. Doors: 4 panel solid timber door. Sanitary fittings: roll top bath, shower unit, toilet and sink.	All finishes. All fixtures and fittings. New window. New door.	
FF3	FF Rear Stair	Floor: Carpet. Ceiling: Plaster painted. Walls: Plaster painted with cornice. Skirting. Windows: 2/2 single glazed timber sash window. Doors: 4 panel solid timber door. Staircase: Timber balustrading.	All finishes. All fixtures and fittings. New staircase and balustrade. New window. New doors.	
FF4	FF Bedroom 2 En-suite	Floor: Tiled. Ceiling: Plaster painted. Walls: Plaster painted and tiled. Window: 2/2 single glazed timber sash window. Doors: 4 panel solid timber door. Sanitary fittings: shower unit, toilet and sink.	All finishes. All fixtures and fittings. New window. New door.	
FF5	FF Bedroom 2 Dressing	Floor: Carpet. Ceiling: Plaster painted. Walls: Plaster painted with cornice. Skirting. Windows: 1 single paned timber casement window. 1 6/6 single paned timber sash window. Doors: 4 panel solid timber door.	All fixtures and fittings. All finishes. New door. New window.	

FF6	FF Bedroom 2	Floor: Carpet. Ceiling: Plaster painted. Walls: Plaster painted with cornice. Skirting. Windows: 1 6/6 single paned timber sash window. Doors: 4 panel solid timber door.	All finishes. All fixtures timber fittings. New window. New window.	
FF7	FF Lobby	Floor: Carpet. Ceiling: Plaster painted. Walls: Plaster painted with cornice and dad rail. Skirting. Windows: 1 6/6 single paned timber sash window possibly original.	All finishes. All fixtures and fittings. New window.	
FF8	FF Bedroom 3	Floor: Carpet. Ceiling: Plaster painted. Walls: Plaster painted with cornice and dado rail. Skirting. Windows: 1 6/6 single paned timber sash window possibly original. Fireplace: Reclaimed fireplace in original opening. 1 6/6 single paned timber sash window possibly original.	All fixture and fittings. All finishes. New doors. New fireplace. New window.	
FF9	FF Bedroom 3 Ensuite	Floor: Tiled. Ceiling: Plaster painted. Walls: Plaster painted with marble to walls. Windows: 1 6/6 single paned timber sash window. Doors: 4 panel solid timber doors. Sanitary: Free standing bath, shower, wc and sink.	All finishes. All fixtures and fittings. New door.	

FF10	FF Stairs	Floor: Carpet. Ceiling: Plaster painted. Walls: Plaster painted with cornice. Skirting. Dado rail. Windows: 1 6/6 single paned timber sash window. Doors: 4 panel solid timber door and door to attic space.	All fixtures and fittings. New window. New stair and balustrade to upper level only.	
FF 11	FF Bedroom 4	Floor: Carpet. Ceiling: Plaster painted. Walls: Plaster painted with cornice and dado rail. Skirting. Windows: 1 6/6 single paned timber sash window possibly original. Fireplace: Reclaimed fireplace in original opening.	All finishes. All fixtures and fittings. New fire place. New door. New window.	
FF12	FF Bedroom 4 En-suite	Floor: Tiled. Ceiling: Plaster painted. Walls: Plaster painted with marble to walls. Doors: 4 panel solid timber doors. Sanitary: Shower, wc and sink.	All fixtures and fittings. All finishes. New door.	
FF13	Hall	Floor: Carpet. Ceiling: Plaster painted. Walls: Plaster painted with cornice. Skirting. Windows: 2 6/6 single paned timber sash windows.	All fixtures and fittings and finishes. New windows. NOTE: Glass balustrading excluded from the application.	

FF14	FF Bedroom 5	Floor: Carpet. Ceiling: Plaster painted. Walls: Plaster painted with cornice and dado rail. Skirting. Windows: 1 6/6 single paned timber sash window possibly original. Fireplace: Reclaimed fireplace in original opening.	All fixtures and fittings. All finishes. New fireplace. New doors. New windows.	
FF15	FF Bedroom 5 En-suite	Floor: Tiles. Ceiling: Plaster painted. Walls: Plaster painted. Doors: Solid timber door Sanitary fittings: Bath, wc and sink.	All finishes. All fixtures and fittings. New door.	
FF16	FF Bedroom 6	Floor: Carpet. Ceiling: Plaster painted. Walls: Plaster painted with cornice and dado rail. Skirting. Windows: 1 6/6 single paned timber sash window possibly	All fixture and fittings. New doors. New windows. New fireplace.	
FF17	FF Bedroom 6 En-suite	Floor: Tiled. Ceiling: Plaster painted. Walls: Plaster painted with marble to walls. Doors: 4 panel solid timber doors. Sanitary: Bath, Shower, wc and sink.	All finishes. All fixtures and fittings. New door. New window.	

Second Floor

Item no.	Room.	Item		Photo record
SF1	SF Stairs	Floor: Carpet. Ceiling: Plaster painted with exposed roof timber painted. Walls: Plaster painted. Stair: Timber stair with wooden door access.	All finishes. New door. NOTE: Glass balustrading excluded from this application.	

SF2	SF Bedroom 1	Floor: Carpet. Ceiling: Plaster painted. Walls: Plaster painted. Skirting. Windows: 3 velux conservation style rooflights	All finishes. All fixtures and fittings. Rooflights. NOTE: Glass balustrading to staircase exluded.	
SF2	SF Bedroom 1 ensuite	Floor: Tiled. Ceiling: Plaster painted. Walls: Plaster painted with marble to walls. Doors: 4 panel solid timber doors. Window: 1 velux conservation style rooflight. Sanitary: Bath, Shower, wc and sink.	All finishes. All fixtures and fittings. Rooflight.	