

Millfields, Hereford street, Presteigne. LD8 2AT

### First floor structure (original bathroom)

# North



- Oak framed, externally mesh and sprayed cement rough render, internally lime plastered lath except where indicated
- Stone external sprayed cement rough render internally lime plastered
- Brick external sprayed cement rough render internally lime plastered
- Wood
- New plasterboard or new plaster
- Soft-board covering a modern wooden frame

