1.	LOWER GROUND FLOOR - LGD01	General Notes	Fire Upgrade Works
	ORIGINAL DOOR TO BE RETAINED		
		 Face fitted (i.e. non rebated) draught-stripping to be installed. Original door furniture to be retained, repaired and overhauled. Where no longer serviceable, new ironmongery to be fitted to match existing pattern and material. Repairs including infill of redundant lock rebates etc to be carried out using hardwood and Repaircare resin system 	 No fire upgrade required - Not a designated fire door
2.	LOWER GROUND FLOOR - LGD02	General Repairs	Fire Upgrade Works
	EXISTING NON-ORIGINAL DOOR TO BE RETAINED		
		 Non-original door furniture to be renewed in heritage antique brass/bronze including new overhead closer. Repairs including infills to redundant lock rebates etc to be carried out using hardwood and Repaircare system Door to be ease and adjusted and non- original frame, linings and architraves to be repaired/renewed as necessary. 	 Existing lining/frames and architraves to be carefully adjusted and refitted to achieve the required FD30S rating. Intumescent brush strip to be rebated into door edge and door rehung on fire rated hinges to match the new ironmongery.

3.	LOWER GROUND FLOOR - LGD03 EXISTING NON-ORIGINAL DOOR TO BE RETAINED	General Repairs	Fire Upgrade Works
		 Non-original door furniture to be renewed in heritage antique brass/bronze including new overhead closer. Repairs including infills to redundant lock rebates etc to be carried out using hardwood and Repaircare system Door to be ease and adjusted and non- original frame, linings and architraves to be repaired/renewed as necessary. 	 Existing lining/frames and architraves to be carefully adjusted and refitted to achieve the required FD30S rating. Intumescent brush strip to be rebated into door edge and door rehung on fire rated hinges to match the new ironmongery.
4.	LOWER GROUND FLOOR - LGD04 EXISTING NON-ORIGINAL DOOR TO BE RENEWED	General Repairs	Fire Upgrade Works
		 Existing MDF bifold door and frame to be renewed in new door and partition to match the adjacent pattern and detailing. New door furniture to be heritage antique brass/bronze including closer. 	 Door, and partition to be renewed to achieve FD30S enclosure of understairs space. New FD30S lining/frames and architraves to be installed Intumescent brush strip rebated into door edge and door hung on fire rated hinges.

5.	LOWER GROUND FLOOR - LGD05 EXISTING NON-ORIGINAL DOOR TO BE RETAINED	General Repairs	Fire Upgrade Works
		 Non-original door furniture to be renewed in heritage antique brass/bronze including new overhead closer. Repairs including infills to redundant lock rebates etc to be carried out using hardwood and Repaircare system Door to be ease and adjusted and non- original frame, linings and architraves to be repaired/renewed as necessary. 	 Existing lining/frames and architraves to be carefully adjusted and refitted to achieve the required FD30S rating. Intumescent brush strip to be rebated into door edge and door rehung on fire rated hinges to match the new ironmongery.
6.	LOWER GROUND FLOOR - LGD06 EXISTING NON-ORIGINAL DOOR TO BE RENEWED	<u>General Repairs</u>	Fire Upgrade Works
		 Existing door and frame split and non-repairable. Door and frame to be renewed in new door and partition to match the adjacent pattern and detailing. New door furniture to be heritage antique brass/bronze including closer. 	 Door, lining, frame and architraves to be renewed to achieve FD30S. Intumescent brush strip rebated into door edge and door hung on fire rated hinges.

7.	<u>GROUND FLOOR – GD01</u> ORIGINAL DOOR TO BE RETAINED	General Repairs	Fire Upgrade Works
		 Redundant signage etc to be removed. Face fitted (i.e. non rebated) draught- stripping to be installed. Original door furniture to be retained, repaired and overhauled. Where no longer serviceable, new ironmongery to be fitted to match existing pattern and material. Repairs including infill of redundant lock rebates etc to be carried out using hardwood and Repaircare resin system 	 No fire upgrade required; Not a designated fire door
8.	GROUND FLOOR - GD02 EXISTING NON-ORIGINAL DOOR TO BE RETAINED	General Repairs	Fire Upgrade Works
		 Non-original door furniture to be renewed in heritage antique brass/bronze including new overhead closer. Repairs including infills to redundant lock rebates etc to be carried out using hardwood and Repaircare system Door to be ease and adjusted and non- original frame, linings and architraves to be repaired/renewed as necessary. 	 Existing lining/frames and architraves to be carefully adjusted and refitted to achieve the required FD30S rating. Intumescent brush strip to be rebated into door edge and door rehung on fire rated hinges to match the new ironmongery.

9.	GROUND FLOOR - GD03 EXISTING NON-ORIGINAL DOOR TO BE RETAINED	General Repairs	Fire Upgrade Works
		 Non-original door furniture to be renewed in heritage antique brass/bronze including new overhead closer. Repairs including infills to redundant lock rebates etc to be carried out using hardwood and Repaircare system Door to be ease and adjusted and non- original frame, linings and architraves to be repaired/renewed as necessary. 	 Existing lining/frames and architraves to be carefully adjusted and refitted to achieve the required FD30S rating. Intumescent brush strip to be rebated into door edge and door rehung on fire rated hinges to match the new ironmongery.
10.	GROUND FLOOR - GD04 EXISTING NON-ORIGINAL DOOR TO BE RETAINED	General Repairs	Fire Upgrade Works
		 Non-original door furniture to be renewed in heritage antique brass/bronze including new overhead closer. Repairs including infills to redundant lock rebates etc to be carried out using hardwood and Repaircare system Door to be ease and adjusted and non- original frame, linings and architraves to be repaired/renewed as necessary. 	 Existing lining/frames and architraves to be carefully adjusted and refitted to achieve the required FD30S rating. Intumescent brush strip to be rebated into door edge and door rehung on fire rated hinges to match the new ironmongery.

11.	GROUND FLOOR - GD05 EXISTING NON-ORIGINAL DOOR TO BE RETAINED	General Repairs	Fire Upgrade Works
		 Non-original door furniture to be renewed in heritage antique brass/bronze including new overhead closer. Repairs including infills to redundant lock rebates etc to be carried out using hardwood and Repaircare system Door to be ease and adjusted and non- original frame, linings and architraves to be repaired/renewed as necessary. 	 Existing lining/frames and architraves to be carefully adjusted and refitted to achieve the required FD30S rating. Intumescent brush strip to be rebated into door edge and door rehung on fire rated hinges to match the new ironmongery.

12.	FIRST FLOOR – 1D01 EXISTING NON-ORIGINAL DOOR TO BE RETAINED	General Repairs	Fire Upgrade Works
		 Non-original door furniture to be renewed in heritage antique brass/bronze including new overhead closer. Repairs including infills to redundant lock rebates etc to be carried out using hardwood and Repaircare system Door to be ease and adjusted and non- original frame, linings and architraves to be repaired/renewed as necessary. 	 Existing lining/frames and architraves to be carefully adjusted and refitted to achieve the required FD30S rating. Intumescent brush strip to be rebated into door edge and door rehung on fire rated hinges to match the new ironmongery.
13.	FIRST FLOOR – 1DO2 EXISTING NON-ORIGINAL DOOR TO BE RETAINED	General Repairs	Fire Upgrade Works
		 Non-original door furniture to be renewed in heritage antique brass/bronze including new overhead closer. Repairs including infills to redundant lock rebates etc to be carried out using hardwood and Repaircare system Door to be ease and adjusted and non- original frame, linings and architraves to be repaired/renewed as necessary. 	 Existing lining/frames and architraves to be carefully adjusted and refitted to achieve the required FD30S rating. Intumescent brush strip to be rebated into door edge and door rehung on fire rated hinges to match the new ironmongery.

14.	FIRST FLOOR - 1D03 EXISTING NON-ORIGINAL DOOR TO BE RETAINED	General Repairs	Fire Upgrade Works
		 Non-original door furniture to be renewed in heritage antique brass/bronze including new overhead closer. Repairs including infills to redundant lock rebates etc to be carried out using hardwood and Repaircare system Door to be ease and adjusted and non- original frame, linings and architraves to be repaired/renewed as necessary. 	 Existing lining/frames and architraves to be carefully adjusted and refitted to achieve the required FD30S rating. Intumescent brush strip to be rebated into door edge and door rehung on fire rated hinges to match the new ironmongery.

15.	SECOND FLOOR – 2D01 EXISTING NON-ORIGINAL DOOR TO BE RETAINED	General Repairs	Fire Upgrade Works
		 Non-original door furniture to be renewed in heritage antique brass/bronze including new overhead closer. Repairs including infills to redundant lock rebates etc to be carried out using hardwood and Repaircare system Door to be ease and adjusted and non- original frame, linings and architraves to be repaired/renewed as necessary. 	 Existing lining/frames and architraves to be carefully adjusted and refitted to achieve the required FD30S rating. Intumescent brush strip to be rebated into door edge and door rehung on fire rated hinges to match the new ironmongery.
16.	SECOND FLOOR – 2DO2 EXISTING NON-ORIGINAL DOOR TO BE RETAINED	General Repairs	Fire Upgrade Works
		 Non-original door furniture to be renewed in heritage antique brass/bronze including new overhead closer. Repairs including infills to redundant lock rebates etc to be carried out using hardwood and Repaircare system Door to be ease and adjusted and non- original frame, linings and architraves to be repaired/renewed as necessary. 	 Existing lining/frames and architraves to be carefully adjusted and refitted to achieve the required FD30S rating. Intumescent brush strip to be rebated into door edge and door rehung on fire rated hinges to match the new ironmongery.

17.	SECOND FLOOR - 2D03 & 2D04 EXISTING NON-ORIGINAL DOOR TO BE REMOVED AND REUSED IN PROPOSED CONFIGURATION	<u>General Repairs</u>	Fire Upgrade Works
		 Doors and frames to be removed and set aside for refitting in proposed configuration. Components to be renewed/repaired as necessary including infills to redundant lock rebates using hardwood and Repaircare system Doors to be refitted using salvaged frame, linings and architraves etc. Non-original door furniture to be renewed in heritage antique brass/bronze including new overhead closer. 	 No fire upgrade required; Not a designated fire door

18.	THIRD FLOOR – 3D01 EXISTING NON-ORIGINAL DOOR TO BE REMOVED	General Repairs	Fire Upgrade Works
		 Non-original entrance door and partition to residential unit to be removed. 	• N/A
19.	THIRD FLOOR – 3DO2 EXISTING NON-ORIGINAL DOOR TO BE REMOVED AND REUSED IN PROPOSED CONFIGURATION	General Repairs	Fire Upgrade Works
		 Doors and frames to be removed and set aside for refitting in proposed configuration. Components to be renewed/repaired as necessary including infills to redundant lock rebates using hardwood and Repaircare system Doors to be refitted using salvaged frame, linings and architraves etc. Non-original door furniture to be renewed in heritage antique brass/bronze including new overhead closer. 	 No fire upgrade required; Not a designated fire door

20.	THIRD FLOOR - 3D04 EXISTING NON-ORIGINAL DOOR TO BE RETAINED	General Repairs	Fire Upgrade Works
		 Non-original door furniture to be renewed in heritage antique brass/bronze including new overhead closer. Repairs including infills to redundant lock rebates etc to be carried out using hardwood and Repaircare system Door to be ease and adjusted and non- original frame, linings and architraves to be repaired/renewed as necessary. 	 Existing lining/frames and architraves to be carefully adjusted and refitted to achieve the required FD30S rating. Intumescent brush strip to be rebated into door edge and door rehung on fire rated hinges to match the new ironmongery.
21.	THIRD FLOOR - 3D05 EXISTING NON-ORIGINAL DOOR TO BE RETAINED	General Repairs	Fire Upgrade Works
		 Non-original door furniture to be renewed in heritage antique brass/bronze including new overhead closer. Repairs including infills to redundant lock rebates etc to be carried out using hardwood and Repaircare system Door to be ease and adjusted and non- original frame, linings and architraves to be repaired/renewed as necessary. 	 Existing lining/frames and architraves to be carefully adjusted and refitted to achieve the required FD30S rating. Intumescent brush strip to be rebated into door edge and door rehung on fire rated hinges to match the new ironmongery.

22.	FOURTH FLOOR – 4DO1 EXISTING NON-ORIGINAL DOOR TO BE RETAINED	General Repairs	Fire Upgrade Works
		 Non-original door furniture to be renewed in heritage antique brass/bronze including new overhead closer. Repairs including infills to redundant lock rebates etc to be carried out using hardwood and Repaircare system Door to be ease and adjusted and non- original frame, linings and architraves to be repaired/renewed as necessary. 	 Existing lining/ frames and architraves to be adjusted and refitted to achieve the required FD30S rating. Intumescent brush strip to be rebated into door edge and door rehung on fire rated hinges to match the new ironmongery.
23.	FOURTH FLOOR - 4D02 ORIGINAL DOOR TO BE RETAINED	General Repairs	Fire Upgrade Works
		 Non-original door furniture to be renewed in heritage antique brass/bronze including new overhead closer. Repairs including infills to redundant lock rebates etc to be carried out using hardwood and Repaircare system Door to be ease and adjusted and non- original frame, linings and architraves to be repaired/renewed as necessary. 	 Existing lining/frames and architraves to be carefully adjusted and refitted to achieve the required FD30S rating. Intumescent brush strip to be rebated into door edge and door rehung on fire rated hinges to match the new ironmongery.

24.	FOURTH FLOOR - 4D03 EXISTING NON-ORIGINAL DOOR	General Repairs	Fire Upgrade Works
	TO BE RETAINED		
	4003	 Non-original door furniture to be renewed in heritage antique brass/bronze including new overhead closer. Repairs including infills to redundant lock rebates etc to be carried out using hardwood and Repaircare system Door to be ease and adjusted and non- original frame, linings and architraves to be repaired/renewed as necessary. 	 Existing lining/frames and architraves to be carefully adjusted and refitted to achieve the required FD30S rating. Intumescent brush strip to be rebated into door edge and door rehung on fire rated hinges to match the new ironmongery.

25.	LG FRONT LIGHTWELL – 4DO1 ORIGINAL DOORS TO BE RETAINED	General Repairs	Fire Upgrade Works
		 Repair and redecorate existing glazed doors and sidelights to vaults including reinstatement of missing detailing (Georgian bars etc) and renewal of glazing in 'Minster' or 'Small Hammered' tempered safety glass. Repairs to be made in hardwood and Repaircare resin system. Door to be ease and adjusted and non- original frame, linings and architraves to be repaired/renewed as necessary. 	Not applicable

26.	VARIOUS LOCATIONS PROPOSED DOORS	General Repairs	Fire Upgrade Works
	LGD.07/P LGD.08/P LGD.09/P	 New doors, frames and mouldings to be installed in to match the adjacent pattern and detailing. New door furniture to be heritage antique brass/bronze including closer. 	Not applicable