



Keys:

	Room works to be done in next Phase of Works - Works not included in this application
	Room works done in previous Phase of Works - Works approved in previous applications
	Room not affected by proposed works

Ground Floor								
Room Reference	Room Name	Floor	Walls	Ceiling	Skirting	Joinery	Doors Inc. Architraves & Linings	Windows Inc. Architraves & Cills
RG01	Entrance Barn	N/A						
RG02	Boot Room	N/A						
RG03	WC	N/A						
RG04	Store	N/A						
RG05	Shower/Steam Room	N/A						
RG06	Sauna	N/A						
RG07	Change Room	N/A						
RG08	Seating Area/Bar	N/A						
RG09	Garden Room	N/A	N/A	N/A	N/A	N/A	New Eclipse Fire rated pocket door DG38 system. Details approved by LPA Ref: 2022/2414/APP	N/A
RG10	Bathroom	N/A						
RG11	Kitchen	Hardwood boards to be laid to extended new areas to match existing flooring	New studwork Fire resistant plasterboard partitions to be finished with skim plaster and paint	Existing suspended plasterboard ceiling to be extended and finished to match existing	Painted MDF Torus skirting board to match existing	N/A	New external Accoya Double door DG28. Details approved by LPA Ref: 2022/2414/APP	N/A
RG12	Bathroom	N/A						
RG13	Dining/Living Room	N/A	N/A	N/A	N/A	N/A	New Eclipse Fire rated pocket door DG37 system. Details approved by LPA Ref: 2022/2414/APP	N/A
RG14	Hallway	N/A						
RG15	Bedroom	N/A						
RG16	Entrance Lobby	N/A						
RG17	Utility	N/A	Existing painted plasterboard walls to be repaired where affected by proposed works	N/A	N/A	N/A	N/A	N/A
RG18	Hallway	N/A	N/A	N/A	N/A	N/A	Existing door DG.14 to be retained and installed in new proposed opening	N/A
RG19	WC	N/A						
RG20	Store	N/A						
RG21	Living Room	N/A						
RG22	Entrance Hall	N/A						
RG23	Library	N/A	N/A	N/A	N/A	N/A	New hardwood & HDF double door DG.29. For details refer to drawing 1279-501	N/A
RG24	Dining Room	N/A	N/A	N/A	N/A	New hardwood & HDF jib door DG.30. For details refer to drawing 1279-501	N/A	N/A
RG25	Larder	N/A	New studwork Fire resistant plasterboard partitions to be finished with skim plaster and paint	Existing suspended plasterboard ceiling to be extended and finished to match existing	Painted MDF Torus skirting board to match existing	N/A	Existing door DG.32 to be retained and installed in new proposed opening	Existing window WG08 to be replaced. Details approved by LPA Ref: 2021/1895/LBC
RG26	Breakfast Area	N/A	N/A	N/A	N/A	N/A	Existing door DG.25 to be retained and installed in new proposed opening New hardwood & HDF door DG.31. For details refer to drawing 1279-502	New Accoya sash window WG.09. For details refer to drawing 1279-550 New Accoya sash window WG.16. For details refer to drawing 1279-550
RG27	Kitchen	600mm width x Random lengths Tumbled Buscot flagstone with Irregular widths mortar joints	New studwork Fire resistant plasterboard partitions to be finished with skim plaster and paint	Plasterboard ceilings fixed to joists to be finished with skim plaster and paint	Painted MDF Torus skirting board to match existing	N/A	New hardwood & HDF double door DG.48. For details refer to drawing 1279-502	New Accoya sash window WG.17. For details refer to drawing 1279-550
RG28	Scullery/Dog Room	600mm width x Random lengths Tumbled Buscot flagstone with Irregular widths mortar joints	New studwork Fire resistant plasterboard partitions to be finished with skim plaster and paint	Plasterboard ceilings fixed to joists to be finished with skim plaster and paint	Painted MDF Torus skirting board to match existing	N/A	New external Accoya door DG50. For details refer to drawing 1279-503	New Accoya sash window WG.18. For details refer to drawing 1279-549
RG29	Kitchen Extension	600mm width x Random lengths Tumbled Buscot flagstone with Irregular widths mortar joints	N/A	42.5mm insulated plasterboard to be fixed under rafters and finished with skim plaster and painted	N/A	N/A	New hardwood & HDF double door DG.54. For details refer to drawing 1279-502 New Velfac bi-fold doors DG.51. For details refer to manufacturer's detail and recommendations.	New Velfac windows WG.19. For details refer to manufacturer's detail and recommendations.
RG30	Dining Room	N/A						
RG31	Kitchen	N/A						
RG32	Bathroom	N/A						



SIMON MORRAY-JONES

Keys:

	Room works to be done in next Phase of Works - Works not included in this application
	Room works done in previous Phase of Works - Works approved in previous applications
	Room not affected by proposed works

First Floor								
Room Reference	Room Name	Floor	Walls	Ceiling	Skirting	Joinery	Doors Inc. Architraves & Linings	Windows Inc. Architraves & Cills
RF01	Gym	N/A						
RF02	Mezzanine	N/A						
RF03	Bedroom	N/A	N/A	N/A	N/A	N/A	N/A	Existing window WF18 to be replaced. Details approved by LPA Ref: 2021/1895/LBC
RF04	Bathroom	N/A						
RF05	Landing	N/A	N/A	Existing painted suspended plasterboard ceiling to be repaired where affected by proposed works	N/A	N/A	N/A	N/A
RF06	Bedroom	N/A	N/A	N/A	N/A	N/A	N/A	Existing window WF17 to be replaced. Details approved by LPA Ref: 2021/1895/LBC
RF07	Bedroom	N/A						
RF08	Bathroom	N/A						
RF09	Bedroom	N/A						
RF10	Landing	N/A						
RF11	Bathroom	N/A						
RF12	Utility	N/A						
RF13	Bedroom	N/A						
RF14	Bathroom	N/A						
RF15	Store	N/A	Studwork plasterboard partitions to be finished with skim plaster and paint and existing plasterboard to be repaired	Existing painted suspended plasterboard ceiling to be repaired where affected by proposed works	Existing skirting to be repaired and new board to be installed where necessary to match existing	N/A	Existing door DF.16 to be re-hung and door lining altered to allow for door leaf to open to the opposite direction	Existing windows WF08 to be replaced. Details approved by LPA Ref: 2021/1895/LBC
RF16	Bathroom	N/A	Studwork plasterboard partitions to be finished with skim plaster and paint and existing plasterboard to be repaired	Existing painted suspended plasterboard ceiling to be repaired where affected by proposed works	Existing skirting to be repaired and new board to be installed where necessary to match existing	N/A	Existing door DF.17 to be retained and installed in new proposed opening	Existing windows WF09 to be replaced. Details approved by LPA Ref: 2021/1895/LBC
RF17	Landing	Hardwood boards to be laid over joists as substrate for new carpeted flooring to match existing	Studwork plasterboard partitions to be finished with skim plaster and paint and existing plasterboard to be repaired	Existing painted suspended plasterboard ceiling to be repaired where affected by proposed works	Existing skirting to be repaired and new board to be installed where necessary to match existing	N/A	N/A	New Accoya Casement window WF.21. For details refer to drawing 1279-551
RF18	Bedroom	N/A	Studwork plasterboard partitions to be finished with skim plaster and paint and existing plasterboard to be repaired	Existing painted suspended plasterboard ceiling to be repaired where affected by proposed works	Existing skirting to be repaired and new board to be installed where necessary to match existing	N/A	Existing door DF.18 to be retained and installed in new proposed opening	Existing window WF11 to be replaced. Details approved by LPA Ref: 2021/1895/LBC
RF19	Bedroom	Hardwood boards to be laid over joists as substrate for new carpeted flooring to match existing	Studwork plasterboard partitions to be finished with skim plaster and paint	42.5mm insulated plasterbord to be fixed under rafters and finished with skim plaster and painted	Torus MDF skiting board painted to match plasterboard walls	N/A	New hardwood & HDF door DF.19. For details refer to drawing 1279-505	New Accoya Casement window WF.22. For details refer to drawing 1279-551
RF20	Bedroom	Hardwood boards to be laid over joists as substrate for new carpeted flooring to match existing	Studwork plasterboard partitions to be finished with skim plaster and paint	42.5mm insulated plasterbord to be fixed under rafters and finished with skim plaster and painted	Torus MDF skiting board painted to match plasterboard walls	N/A	New hardwood & HDF door DF.20. For details refer to drawing 1279-505	New Accoya Casement window WF.23. For details refer to drawing 1279-551

Second Floor								
Room Reference	Room Name	Floor	Walls	Ceiling	Skirting	Joinery	Doors Inc. Architraves & Linings	Windows Inc. Architraves & Cills
RS01	Bedroom	New hardwood boards to be laid over existing rafters as substrate for new carpeted flooring to match existing	Studwork plasterboard partitions to be finished with skim plaster and paint	42.5mm insulated plasterbord to be fixed under rafters and finished with skim plaster and painted	Torus MDF skiting board painted to match plasterboard walls	N/A	New hardwood & HDF door DS.04. Details approved by LPA Ref: 2022/2414/APP	New Accoya Casement window WS.06. Details approved by LPA Ref: 2022/2414/APP
RS02	Landing	New hardwood boards to be laid over existing rafters as substrate for new carpeted flooring to match existing	Studwork plasterboard partitions to be finished with skim plaster and paint	42.5mm insulated plasterbord to be fixed under rafters and finished with skim plaster and painted	Torus MDF skiting board painted to match plasterboard walls	N/A	N/A	N/A
RS03	Bathroom	New hardwood boards to be laid over existing rafters as substrate for new carpeted flooring to match existing	Studwork plasterboard partitions to be finished with skim plaster and paint	42.5mm insulated plasterbord to be fixed under rafters and finished with skim plaster and painted	Torus MDF skiting board painted to match plasterboard walls	N/A	New hardwood & HDF door DS.05. Details approved by LPA Ref: 2022/2414/APP	New Accoya Casement window WS.05. Details approved by LPA Ref: 2022/2414/APP
RS04	Bedroom	N/A						
RS05	Bathroom	N/A						
RS06	Landing	N/A						
RS07	Bedroom	N/A						