


GENERAL NOTES ON WINDOWS:

- W1 - to be repaired and refurbished
- W2 - to be repaired and refurbished
- W3 - to be repaired and refurbished
- W4 - to be replaced with white painted timber framed single glazed sash to match originals (W8 + W14)
- W5 - to be repaired and refurbished
- W6 - to be repaired and refurbished
- W7 - to be repaired and refurbished
- W8 - to be repaired and refurbished
- W9 - to be repaired and refurbished
- W10 - to be repaired and refurbished
- W11 - to be repaired and refurbished
- W12 - to be repaired and refurbished
- W13 - enlarged opening an new white painted timber framed double glazed casement
- W14 - to be repaired and refurbished
- W15 - to be repaired and refurbished
- W16 - to be repaired and refurbished
- W17 - enlarged opening an new white painted timber framed double glazed casement

**GENERAL NOTES:
GENERAL REPAIR AS
REQUIRED TO ROOF
TILES, LEAD FLASHINGS,
RAINWATER GOODS,
TIMBER CLADDING,
RENDER AND BRICK
POINTING.**

**GENERAL NOTES:
ALL BLUE DOTTED LINES
NOTE PROPOSED
LINTELS TO SE
SPECIFICATION**

**GENERAL NOTES:
ALL RED DOTTED LINES
NOTE AREAS OF
DEMOLITION**



Enlarged opening and new timber framed double glazed casement window (to be painted white)
New lintel needed to Structural Engineer specification

New steel balcony with decorative metal gratings (to be painted black) to garden elevation
to Structural Engineer specification

New steel balcony supports, painted black

Enlarged opening and new timber framed double glazed casement window (to be painted white) and partially opaque glazing
New lintel needed to Structural Engineer specification

Existing ground floor window to be repaired and refurbished
New lintel needed to Structural Engineer specification

New shower room external wall to be white painted brickwork

+19640 ridge

+18074 parapet

+14480 second FFL

+12030 first FFL

+10000 ground FFL

+7480 basement FFL