
Mode Engineers



Lime Tree Farm Ipswich Road Long Stratton Norfolk

Design Access Statement

Document reference: 22-38-DAS-01-00

Revision:	Description:	Date:
00	Original Issue	14/02/2023

1.0 Contents

		Sheet No.
1.0	Contents	1
2.0	Property Address	1
3.0	Property Description	1
4.0	Proposed Works	1
5.0	Consultation	2
6.0	Design & Access Components	2
7.0	Historic Building Conservation	2
8.0	Annex A - Listed Building Record	3
9.0	Annex B - Photographs	4

1.0 Property Address

1.1 Lime Tree Farm

Ipswich Road

Long Stratton

Norfolk

NR15 2AX

3.0 Property Description

3.1 Lime Tree farm is situated approximately 1 mile due south of Long Stratton on the eastern side of the A140. The site is comprises several farm buildings, trees, gardens and the main farmhouse. The main farmhouse was constructed in two phases dating from 18th century and is grade II listed in 1976. Quoting from the Norfolk Heritage Explorer website the property is described as:

An early 18th century plastered clay lump house with an 18th or 19th century wing in painted brick. The house has brick chimney stacks and a 19th century pilastered doorcase.

Probably early 18th century. Plastered clay lump. Pantile roof with gable ends. Two storeys. Two widely spaced windows, three-light casements with later dripmoulds, central early 19th century pilastered doorcase with panelled door. Adjoining south at right angles an 18/19th century wing, painted brick, brick dentil eaves, pantile hipped roof, two storeys, two windows facing south, casements, pilastered doorcase. Brick chimney stacks.

4.0 Proposed Works

4.1 The works the client wishes to carry out are summarised as follows:

- 1. Repairs to the timber frame section of the main farmhouse including under-pinning
- 2. Demolish and rebuild the lean-to bathroom on the eastern elevation to improve access and bring up-to current standards
- 3. Extend the kitchen on the eastern gable elevation
- 4. Construct a workshop/gym in the garden
- 5. Provide additional access from the A140

\bigwedge	Mode E	Engineers	Heigham Street Norwich, Norfolk NR2 4TE	www.modeengineers.com info@modeengineers.com 01603 975285
	Lime Tree Farm, Ipswich Road, Long Stratton			
	job no. 22-5	38	date	February 2023
\vee	SW	/B approved		sheet no. 1

5.0 Consultation

5.1 At present the client has consulted Mode Engineers relating to the condition of the existing property and the feasibility of the proposed developments. Prior to submission of the planning application relevant parties will be consulted.

6.0 Design & Access Components

- 6.1 The older timber framed part of the property is currently in state of disrepair with defects to the fabric and the structure which comprise its habitability presently and its structural stability going forward. Defects include but are not limited to:
 - Compromised cross beam in the living (ref annex A)
 - Absence of foundations and damp-proof course (ref annex A)
 - Rotted timbers including the sole plate and tenoned timber posted (ref annex A)
 - Impermeable OPC render causing cracking and damp ingress (ref annex A)
 - Settlement to the north-west corner (ref annex A)

It's the owner's intention to carry out the remedial works for the items listed above. Clay lump infill would be replaced with hemp insulation and external carrier board rendered with a lime plaster. The external appearance would not be altered with existing features such as doors being repaired and windows replaced with matching alternative

- 6.2 The lean-to bathroom on the east elevation is a later addition, currently in state of disrepair and not performing its intended function. The lean-to is to be demolished and rebuilt with matching plan dimensions. Wider doorways providing disability access will be provided. Timber cladding, like that in place, will be used for the walls. The roof covering will be troughed metal sheeting, as is present.
- 6.3 The kitchen extension to the east gable elevation measures 4940 x 4040 mm on plan. Eaves height is 2500 mm, ridge height is 4380 mm and the roof pitch will match that of the existing roof. Material use will be sympathetic to the existing building; walls constructed of red flettons painted to match the existing property, clay pan tiles used for the roof. Opening between the existing property will be via existing window opening taken down to ground level.
- 6.4 Construction of a workshop and gymnasium in the garden beyond the rear of the property. The structure will be lightweight timber built off shallow foundations. Bounding dimensions are 7625 x 14285 mm, usable floor area of 72 m² and eaves height of 2790 mm. Vertical timber cladding with a section floor to ceiling glazing on the east elevation. Access for the delivery materials will provided via a new driveway. None of the tree on site will be affected.
- 6.5 Provision of new highway access to the south-east corner of the property on to the A140. The road is relatively straight along this section of the A140 with visibility in both directions. The hedge would be removed to create the access.

7.0 Historic Building Conservation

- 7.1 The failing oak beam in the living room, which is currently propped at mid span, will be replaced with a new oak beam. The original timber will be used elsewhere in the restoration of the property.
- 7.2 Conservation work to the timber frame will be carried out with due regard for the historic features of the property. The pilastered doorcase will be repaired and restored. Rotten timbers will be replaced with new timbers scarfed in. The introduction of a DPC will ensure the sole plate remains free from damp, which as been the cause of damage to the timber frame.
- 7.2 Introduction of a breathable building fabric will decrease damp in the property and seasonal variation in the moisture content of the timbers causing movement which damages finishes. Improved thermal performance will decrease the financial and environmental operating costs of the property.
- 7.4 Underpinning due to lack of substantive foundations will remediate the settlement in the north-west corner of the property and facilitate the introduction of an insulated floor slab.

$\wedge \wedge$	Mode	Eng	ineers	Heigham Street Norwich, Norfolk NR2 4TE	www.modeengineers.com info@modeengineers.com 01603 975285
	Lime Tree Farm, Ipswich Road, Long Stratton				
	job no.	22-38		date	February 2023
\vee	engineer	SWB	approved		sheet no. 2

Home | Site Map | Sign In

Home

News

Projects

Schools

FAQs

Links

Print Friendly Norfolk Heritage Explorer Show on map Search Records **Record Details** NHER Number: 44398 Building Type of record: Name: Limetree Farmhouse, Ipswich Road Summary **Exploring More** An early 18th century plastered clay lump house with an 18th or 19th century wing in painted brick. The house has **Out & About** brick chimney stacks and a 19th century pilastered doorcase. Images - none Heritage Glossary Location Grid Reference: TM 19331 90172 **Contact Us** Map Sheet: TM19SE Parish: LONG STRATTON, SOUTH NORFOLK, NORFOLK **Terms & Conditions Full description** September 1976. Listed, Grade II. Probably early 18th century. Plastered clay lump. Pantile roof with gable ends. Two storeys. Two widely spaced windows, three-light casements with later dripmoulds, central early 19th century pilastered doorcase with panelled door. Adjoining south at right angles an 18/19th century wing, painted brick, brick dentil eaves, pantile hipped roof, two storeys, two windows facing south, casements, pilastered doorcase. Brick chimney stacks. Information from (S1). A. Cattermole (NLA), 13 April 2006.

Monument Types

• FARMHOUSE (17th Century to 21st Century - 1700 AD to 2100 AD)

Associated Finds - none

Protected Status

Listed Building

Sources and further reading

Designation: Historic England. National Heritage List for England. List Entry 1153579. ----

Related records - none

Find out more...

Parish Summary: Long Stratton (Parish Summary)

Norfolk County Council



Powered by HBSMR-web and the HBSMR Gateway from exeGesIS SDM Ltd, and mojoPortal CMS © 2007 - 2023 Norfolk Historic Environment Service

$\wedge \wedge$	Mode	Eng	ineers	Heigham Street Norwich, Norfolk NR2 4TE	<u>www.modeengi</u> info@modeeng 01603 97	neers.com
	Lime Tree Farm, Ipswich Road, Long Stratton					
	job no.	22-38		date	February 2023	3
\vee	engineer	SWB	approved		sheet no.	3

9.0 Annex B – Photographs



Figure 1 West Elevation



Figure 2 West Elevation

$\wedge \wedge$	Mode Eng	gineers	Heigham Street Norwich, Norfolk NR2 4TE	www.modeengineers.com info@modeengineers.com 01603 975285	
	Lime Tree Farm, Ipswich Road, Long Stratton				
	job no. 22-38		date	February 2023	
\vee	engineer	approved		sheet no. 4	



Figure 3 East Elevation



Figure 4 East Elevation

$\wedge \wedge$	Mode Eng	fineers	Heigham Street Norwich, Norfolk NR2 4TE	www.modeengineers.com info@modeengineers.com 01603 975285
MM	Lime Tree Farm, Ipswich Road, Long Stratton			
	job no. 22-38		date	February 2023
\bigvee	engineer	approved		sheet no. 5



Figure 5 North Elevation



Figure 6 South Elevation

Mode Eng	ineers	Heigham Street Norwich, Norfolk NR2 4TE	www.modeengineers.com info@modeengineers.com 01603 975285	
Lime Tree Farm, Ipswich Road, Long Stratton				
job no. 22-38		date	February 2023	
swB	approved		sheet no. 6	
	project job no. SWB	project Lime Tree Farm, Ipswich Road job no. 22-38 SWB	project Lime Tree Farm, Ipswich Road, Long Stratton 22-38 date SWB	



Figure 7 Pilastered Door



Figure 8 Propped Beam

$\wedge \wedge$	Mode Eng	ineers	Heigham Street Norwich, Norfolk NR2 4TE	www.modeengineers.com info@modeengineers.com 01603 975285	
\square	project Lime Tree Farm, Ipswich Road, Long Stratton				
	job no. 22-38		date	February 2023	
\lor	swB	approved		sheet no. 7	



Figure 9 Trial Pit - No Foundations



Figure 10 Cracking in North-West Corner

	Mode Eng	gineers	Heigham Street Norwich, Norfolk NR2 4TE	<u>www.modeengir</u> info@modeengir 01603 975	neers.com
	Lime Tree Farm, Ipswich Road, Long Stratton				
	job no. 22-38		date	February 2023	
\vee	engineer	approved		sheet no.	8