


Note: No timber frame repairs
required on this elevation



Rake out loose debris and
drive slate course below
existing sole plate as DPC.