

**PHOTOGRAPHS -  
GUEST AMENITY AREAS  
PEACOCK LAKE GLAMPING  
5 PEACOCK CLOSE  
GUNTHORPE  
NOTTINGHAM  
NG14 7RA**



**1. The front north west facing view of the guest amenity areas viewed from the gravel drive and parking area.**



2. The front north west facing elevation with canopy of the amenity building – south west end.



3. The front north west elevation of the amenity building (games room) – north east end.





**4. The pergola structure in front of the amenity building north east end.**



**5. The north east gable end of the amenity building (glazed doors into games room).**



**6. The timber boarded gate at the rear east corner of the amenity building.**



**7. The timber screen fence at the north east side of the amenity building.**



8. Outside the timber north east screen fence.



9. Looking west down the front covered path under the canopy roof.





10. Looking west further under the front covered path.



11. The south end of the amenity building adjacent to the second amenity building.



12. The south west gable end of the amenity building.



13. Sheds in the south corner back yard.





14. The rear south corner of the amenity building and small shed.



15. The rear south east facing rendered wall of the amenity building.





16. The corner junction between the amenity building and smaller front amenity cabin.



17. The games room in the east end of the amenity building.



18. The bar and kitchen door at the rear south corner of the games room.



19. The kitchen (used as store room) with rear south east facing small window.





20. Looking into the utility room through the external door.



21. Looking into the toilet room through the external door.



22. Looking into the front south store room through the pair of timber double doors.



23. The rear workshop store room behind the above south store room.





24. The front north east facing elevation of the front amenity cabin building.



25. The north west end of the cabin amenity building and rear timber fence.



26. The metal and timber raised front deck with steps.



27. The large window in the south east end of the amenity cabin building.





28. Looking west along the rear elevation of the cabin building.



29. The rear west corner of the cabin building and west end fence.



30. Looking north west along the entrance drive from the gravel car parking area.



31. The south east end of the entrance drive onto the gravel car parking area.

END.