

Roundabout Cottage, 62 High Street



**PHOTO 1 – Principal (South) Elevation including 7no. windows and front door to be replaced.**



**PHOTO 2 – Side (Eastern) Elevation including side door to be replaced.**

Roundabout Cottage, 62 High Street



**PHOTO 3 – Side door to be replaced on Eastern Elevation**



**PHOTO 4 – Rear (North) Elevation 1no. window to be replaced.**

Roundabout Cottage, 62 High Street



**PHOTO 5 – Front door on Principal (South) elevation.**



**PHOTO 6 – Evidence of warped front door no longer closing properly.**

Roundabout Cottage, 62 High Street



**PHOTO 7 – Side door decay and warping causing issues closing.**



**PHOTO 8 – Criminal damage to first floor window on principal elevation**

Roundabout Cottage, 62 High Street



**PHOTO 9 – Criminal damage to first floor window on principal elevation**



**PHOTO 10 – Criminal damage to ground floor window on principal elevation**